Submit 3 Copies

APPROVED BY_

CONDITIONS OF APPROVAL, IF ANY:

State of New Mexico Energy Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

to Appropriate District Office	Elicity, withcrais and water a	tesources Department	VCARSCR 1-1-	37
DISTRICT I P.O. Box 1980, Hobbs NM 88240	OIL CONSERVATION DIVISION P.O. Box 2088		WELL API NO. 30-025-11774	
DISTRICT II P.O. Drawer DD, Artesia, NM 88210				EE 🗌
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No.	EEU
CLINDDY NO	TICES AND REPORTS ON WEL	15	B-11478	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name SOUTH JUSTIS UNIT	
1. Type of Well: OIL GAS WELL X WELL	OTHER		,	
2. Name of Operator			8. Well No.	
ARCO Permian			24	
3. Address of Operator P.O.BOX 1610, MIDLAND, TX 79702			9. Pool name or Wildcat JUSTIS BLBRY-TUBB-DKRD	
4. Well Location		Line and 6600	Feet From The EAST	Line
Unit Letter H : 165				County
Section 25	Township 25S F	Range 37E her DF, RKB, RT, GR, et	NMPM LEA	7//////
	3065.5 GR		X/////////////////////////////////////	
11. Check A	ppropriate Box to Indicate	Nature of Notice	, Report, or Other Data	
	INTENTION TO:	SU	BSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING			IG OPNS. PLUG AND ABANDON	MENT L
PULL OR ALTER CASING CASING TEST AND C			CEMENT JOB	
OTHER: ADD B-T-D PERFS &	TREAT	OTHER:		
12. Describe Proposed or Completed C work) SEE RULE 1103.	Operations (Clearly state all pertinent d	etails, and give pertinent d	dates, including estimated date of starting any	y proposed
PROPOSE TO: 1. CO TO 6100. 2. ADD BLBRY-TUBB-DI 3. ACID TREAT. 4. RIH W/ CA.	KRD PERF TO EXISTING PE	RFS.		
I hereby certify that the information above	is true and complete to the best of my knowle	edge and belief.		
SIGNATURE Ken W So	snell	TITLE AGENT	DATE 03-24-	95
TYPE OR PRINT NAME Ken W. Gos	inell		TELEPHONE NO.915 6	<u>88-5677</u>
	IAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR		MAR 3 0	1995
ADDROVED BY		TITLE	DATE	

WORKOVER PROCEDURE

DATE: March 21, 1995

WELL & JOB: SJU H-24

DRILLED: 1959

LAST WORKOVER: 10/93 Pulled Prod Equipment & SI FIELD: Justis

COUNTY: Lea, NM

BY: W. C. Heard

TD: 8280'

PBD: 6805'

DATUM: 12' KB

CASING: SURFACE: **INTERMEDIATE:** PROD:

32.3/36# 20/23#

GRADE H40 H40/J55 J55/N80

3**335**'

SX CMT 550 1700 623

PERFORATIONS: Open perfs: Blinebry 5030-5560'; plugged perfs; Montoya 6915-6974' (CIBP @ 6840' w/35' cement on top). Ellenburger 8235-8252' (Mod D pkr w/DR plug @ 8210')

TUBING: SIZE:

WEIGHT:

GRADE:

THREAD:

JOINTS:

BTM'D@

MISC:

HISTORY AND BACKGROUND: During workover of 10/93, pulled and LD all production equipment, SI well. No other work performed since 10/93. (Note: check Production files to verify)


SCOPE OF WORK: Add perfs, acidize new and old perfs, install production equipment.

PROCEDURE

- MIRU PU. Install BOP. 1.
- TIH with bit and clean out to 6100'. POH. 2.
- RU WL and add attached perfs. Correlate to Schlumberger Gamma Ray Neutron Log dated 4/10/59. 3.
- TIH with packer and RBP. Acidize old and new perfs as per attached treatment procedure. POH. 4.
- Run CA as per Production Department design and TOPS. 5.

W. C. Heard

WELLBORE SCHEMATIC



O/A Engineering, KEG SJUH24.XLS

