

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B-11478	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> ** GAS WELL <input type="checkbox"/> OTHER- **Dual: Blinebry/Montoya		7. Unit Agreement Name
2. Name of Operator Atlantic Richfield Company		8. Farm or Lease Name State "Y"
3. Address of Operator P. O. Box 1978, Roswell, New Mexico 88201		9. Well No. 7
4. Location of Well UNIT LETTER A , 430 FEET FROM THE North LINE AND 760 FEET FROM THE East LINE, SECTION 25 TOWNSHIP 25-S RANGE 37-E NMPM.		10. Field and Pool, or Wildcat Justis: Blnbry/Mont.
15. Elevation (Show whether DF, RT, GR, etc.) GL Elev = 3073'		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Production from each zone in this dual well has declined to 3 BOPD. We propose to treat existing Montoya perforations w/7000 gallons of 15% HCl acid. Treat existing Blinebry perforations 5366-5432' (Schl.) w/30,000 gallons of lease oil and 30,000# of 20/40 sand. Perforate additional Blinebry pay w/one 3/8" jet shot @ 5199, 5200, 5201, 5203, 5204, 5228, 5259, 5314, 5316, 5318 & 5319 (11 holes) and treat w/1000 gallons of 15% HCl acid, 20,000 gallons of lease oil & 24,000# of 20/40 sand. Completion assembly will be run as installed originally except that dual packer will not be used.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Original Signed
O. D. Bretches TITLE Dist. Drlg. Supervisor DATE 3-26-68

APPROVED BY [Signature] TITLE DATE

CONDITIONS OF APPROVAL, IF ANY: