

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> ** GAS WELL <input type="checkbox"/> OTHER- **Dual: T/Dkd & Fusselman		7. Unit Agreement Name
2. Name of Operator Atlantic Richfield Company		8. Farm or Lease Name State "Y"
3. Address of Operator P. O. Box 1978, Roswell, New Mexico 88201		9. Well No. 8
4. Location of Well UNIT LETTER <u>41</u> , <u>111</u> FEET FROM THE <u>71</u> LINE AND <u>710</u> FEET FROM THE <u>6</u> LINE, SECTION <u>24</u> TOWNSHIP <u>24</u> RANGE <u>31</u> NMPM.		10. Field and Pool, or Wildcat Justis**
15. Elevation (Show whether DF, RT, GR, etc.)		12. County Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	T/Dkd zone
PULL OR ALTER CASING <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
OTHER <u>Recomplete in Blinebry zone</u> <input checked="" type="checkbox"/>	

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

This well is presently dually completed in Fusselman and Tubb/Drinkard zones. The Tubb/Drinkard is producing from perforations 5902-5925 and is producing approximately 3 BOPD, & 4 BWPD. We propose to abandon the Tubb/Drinkard zone by squeeze cementing all perforations; recomplete in the Blinebry by perforating w/one 3/8" JS @ 5178, 5185, 5201, 5267, 5280, 5291, 5299, 5365, 5379, 5425, 5433, 5447, stimulate these perforations w/2500 gal 15% HCl acid, 30,000 gal lease crude containing 36,000# sand. No change will be made in Fusselman packer setting or tubing. Blinebry will be completed thru open ended 2" tubing.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Original Signed
SIGNED O. D. Bretches TITLE Dist. Drlg. Supervisor DATE 4-22-68

APPROVED BY [Signature] TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

F/L For D C Broken