

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT (Other
verse side)TRIP
ationATE
re-Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

032579(e)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME Fed. Lease
2. NAME OF OPERATOR Westates Petroleum Company	8. FARM OR LEASE NAME Carlson B 25
3. ADDRESS OF OPERATOR Box SS, Jal, New Mexico	9. WELL NO. 2
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 990' PSL and 660' PSL Sec. 25	10. FIELD AND POOL, OR WILDCAT Justis Bline-Tubb Drk.
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3054
	12. COUNTY OR PARISH Los
	13. STATE New Mex.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

3-19-69 - Current Status: Dual 7" 23# at 5915.60'. Blinebry perfs. 5004-28', 5038-58', 176 holes. 5268-78', 20 holes, 5446-68', 88 holes. Tubb Drk. Perf. 5722-42', 5755-79', 5794-5824', 300 holes.

3-25-69 - We propose to pull both strings of tubing. Perf. Blinebry zones as follows with 2 jts in each: 5089-5101, 5179-82', 5194-96', 5309-11'. Set BP about 5400' and full bore at 5080'. Pump into 20 old holes at 5268-78' and new perfs. Divert acid treatment with ball sealers. Retrieve BP and packer. Run both strings of tubing for production and swab in both wells.

18. I hereby certify that the foregoing is true and correct

SIGNED

W. Z. Stull

TITLE

Prod. Supt.

DATE

3-19-69

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.