

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other instructions on re-
verse side)Form approved
Budget Bureau No. 42-R1424
5. LEASE DESIGNATION AND SERIAL NO.

LC 032579 (e)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME Fed. Lease
2. NAME OF OPERATOR Westates Petroleum Company	8. FARM OR LEASE NAME Carlson B-25
3. ADDRESS OF OPERATOR 1600 Broadway, Suite 2360 - Denver, CO 80202	9. WELL NO. 5
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit 0 SW $\frac{1}{4}$ SE $\frac{1}{4}$ 25-25S-37E	10. FIELD AND POOL, OR WILDCAT Justis Tubb-Drinkard
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Section 25-25S-37E
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3054 DF	12. COUNTY OR PARISH Lea
	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	☐	PULL OR ALTER CASING	☐
FRACTURE TREAT	☐	MULTIPLE COMPLETE	☐
SHOOT OR ACIDIZE	☐	ABANDON*	☐
REPAIR WELL	☐	CHANGE PLANS	☐
(Other) Temporary Abandonment			

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	☐	REPAIRING WELL	☐
FRACTURE TREATMENT	☐	ALTERING CASING	☐
SHOOTING OR ACIDIZING	☐	ABANDONMENT*	☐
(Other)			

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)


17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

The Tubb-Drinkard zone was no longer commercial and was plugged back with a cast iron bridge plug on March 30, 1969, as per attached copy of Form 9-331, approved May 6, 1969.

We have no plans to re-open this zone at this time.

18. I hereby certify that the foregoing is true and correct

SIGNED



TITLE

Area Manager

DATE

10/21/74

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

DATE

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other Instr. on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for permits to drill or to deepen or plug back to a different reservoir.
Use APPLICATION FOR PERMIT (for such proposals.)

6. LEASE DESIGNATION AND SERIAL NO.

032579(2)

7. IF INDIAN, ALLOTTEE, OR TRIBE NAME

7. UNIT AGREEMENT NAME

Fed. Lease

8. FARM OR LEASE NAME

Carlson B 25

9. WELL NO.

5

10. FIELD AND TOOL OR WILDCAT

Justin Blinco, Tubbs Crk.

11. SEC. T. R. S. AND SURVEY OR AREA

Sec. 25-25-27

12. COUNTY AND STATE

Lee N. Mex.

1. OIL WELL ☒ GAS WELL ☐

2. NAME OF OPERATOR

Westates Petroleum Company

3. ADDRESS OF OPERATOR

Box 33, Jal, New Mexico

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

990 FSL 1970 FSL Sec. 25

14. PERMIT NO.

15. ELEVATIONS (Show whether of, at, or, etc.)

3054 D. P.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☒

(Other)

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(Note: Report results of multiple completion or Well Completion or Recompletion Report and Log.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent notes, including as to any directional drilling, give subsurface locations and measured and true vertical depths for all zones pertinent to this work.)

3-30-69 - Set Baker cast iron plug #5500' with 10' cement cap temporary abandon Tubbs zone.

Perforated Blinbry zone as follows with 1/2" holes, one hole per int. 5221'-5239'-5247'-5255'-5265'-5280'. Set bridge plug at 5355'. Set fullbore packer #5108'. Acidize Blinbry zone with 5000 gal. 15% acid. Run tubing, put well back on production from Blinbry zone only.

18. I hereby certify that the foregoing is true and correct

SIGNED W. F. Still

TITLE Prod. Supt.

DATE 5-5-72

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL IF ANY:

TITLE

DATE

APPROVED

*See Instructions on Reverse Side

ACTING DISTRICT ENGINEER