	N. M. OIL CONS. CDWY TATES P. O. BOX 1980 THE INTERIORHOBBS. NEW MEXICO MANAGEMENT			
SUNDRY NOTICES AND Do not use this form for proposals to drill or to Use "APPLICATION FOR PEF	deepen or reentry to a different reservo	LC 03259 (c) - <u>LC-032579</u> ir. <sup>6.</sup> IF INDIAN, ALLOTTEE OR TRIBE NAME		
SUBMIT IN TRI	7. IF UNIT OR CA, AGREEMENT DESIGNATION			
I. TYPE OF WELL OIL GAS WELL OT	8. WELL NAME AND NO. South Justis Unit "D" #25			
2. NAME OF OPERATOR ARCO Oil & Gas Company 3. ADDRESS AND TELEPHONE NO.		9. API WELL NO. 30-025-11797		
P.O. Box 1610, Midland, TX 79702 4. LOCATION OF WELL (Footage, Sec., T., R., M., or Survey	(915) 688-5672	10. FIELD AND POOL, OR EXPLORATORY AREA Justis Blbry-Tubb-Dkrd		
2310 FSL & 330 FEL (Unit Letter I) 26-25S-37E		11. COUNTY OR PARISH, STATE		
12. CHECK APPROPRIATE BOX(S)	TO INDICATE NATURE OF NOTICE, REI	PORT, OR OTHER DATA		
TYPE OF SUBMISSION	TYPE OI	FACTION		
SUBSEQUENT REPORT	ABANDONMENT     RECOMPLETION     PLUGGING BACK	CHANGE OF PLANS  NEW CONSTRUCTION  NON-ROUTINE FRACTURING  WATER SHUT-OFF		
FINAL ABANDONMENT NOTICE	(NOTE: Report	CONVERSION TO INJECTION <u>refor South Justis Unit</u> reults of multiple completion on Well or Recompletion Report and Log form.)		
3. DESCRIBE PROPOSED OR COMPLETED OPERATIONS ( proposed work. If well is directionally drilled, give subsur Propose to workover wellbore for South Just	face locations and measured and true vertical depth			
<ol> <li>POH w/CA.</li> <li>Drill out cmt &amp; CIBP @ 5580</li> <li>Drill out cmt &amp; CIBP @ 5835</li> <li>Mill over &amp; fish Model "D" p</li> <li>Press test csg to 500# for 30 n</li> <li>Add perforations &amp; stimulate.</li> <li>RIH w/CA.</li> </ol>	kr @ 5850.	SEP T IL 19 MM 193		
14. I hereby certify that the foregoing is true and correct signed Ken & Lofnell	TITLE AGENT	DATE 9-2-93		
(This space for Federal or State office use)	Patrolanon Pro			
APPROVED BY CONDITIONS FOR APPROVAL, IF ANY:	TITLE d'uses un interior alle	DATE <u>1/2//95</u>		

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

## WORKOVER PROCEDURE

DATE:8/12/93

WELL & JOB: SJU "D" #25

## **DRILLED:** 1/60

LAST WORKOVER: 1/92 Replace Pump			FIELD	FIELD: South Justis Unit		COUNTY: Lea, NM
<b>BY:</b> R. D. Re	ynolds	<b>TD:</b> 6250'	PBD:	5564'	DATUM	I: Unknown
TUBINGHEAI	<b>):</b> Unknown		SIZE:		PRESS	RATING:
CASING: SURFACE: INTER:	<u>SIZE</u> 11-3/4"	<u>WEIGHT</u> 42	<u>GRADE</u> H-40	<u>SET @</u> 851'	<u>SX CM</u> 700	<u><b>T</b></u> <u>TOC</u> surface
PROD:	7"	23	N/J	6249'	700	Unknown

**PERFORATIONS:** Blinebry- 5054'-98', 5131'-38', 5218'-5388', Tubb- 5764'-76' & 5794'-5804', Drinkard- 5880'-5930'. Squeezed perfs.- 5948'-6202'

 TUBING:
 SIZE:
 2-3/8"
 WEIGHT:
 4.7
 GRADE:
 J-55
 THREAD:
 EUE

 BTM'D @
 5450'
 JOINTS:
 178
 MISC:
 THREAD:
 EUE

**PACKER AND MISC:** Fish: Model D pkr. with C-3 receptacle (note: this could be a CL or CR seal assembly, 4-1/4" x 3-13/16") tailpipe and SN at 5886'.

**HISTORY AND BACKGROUND:** This well was originally drilled and completed as a dual Drinkard and Blinebry producer. 11/62 Tubb perforations were added and treated. The Drinkard and Tubb were produced below a packer and the Blinebry was produced up the short side tubing. 5/68 The Drinkard was abandon with a CIBP at 5835' and 11' of cement. Additional Blinebry perforations were added and the dual completion assembly rerun. 1/71 The Tubb was abandon with a CIBP at 5580' with 16' of cement. The well was completed as a single rod pump well from the Blinebry perforations.

SCOPE OF WORK: Clean well out to original PBTD of 6230' and bring into unit.

## PROCEDURE

- 1. MIRUPU. POH with rods and pump (unseat pump and hot water as necessary). ND wellhead and NU BOP with 2-7/8" rams.
- 2. TIH with 6-1/8" MT bit, DC's and 2-7/8" WS to top of Blinebry perforations at 5054'. Load hole and break circulation using bridging material. Continue in hole and drill out cement and CIBP at 5580'.

- 3. Continue in hole and drill out cement and CIBP at 5835'. Continue in hole to C seal receptacle. POH.
- TIH with 6-1/8" x 4-5/8" KR shoe, 1 jt. of 5-1/2" WP, top bushing, jars and 4-1/4" DC's. Cut 4. over Model D packer at 5850' (note: tailpipe below packer) and push to bottom. TOH.
- TIH with 5-7/8" OD overshot with extension and 4-3/8" grapple to catch Model D packer body. 5. POH.
- If tailpipe is left in hole, washover with 6-1/8" KR shoe and 5-1/2" WP. Cut core and retrieve fish. 6.
- TIH with 5-1/2" FB packer and set at 5000' ±. Pressure test annulus to 500 psi. Acidize Blinebry, 7. Tubb and Drinkard perforations.
- Add perforations and stimulate. Release packer and POH, laying down 2-7/8" WS. Change rams from 2-7/8" to 2-3/8". 8.
- TIH with completion assembly per F/P Engineering design. ND BOP and NU wellhead. Run pump and 9. rods. Space out, pressure test tubing to 500 psi and check pump action.
- 10. RDPU and TOTP.

RDR R. D. Reynolds

A 3/13/73 J. Shields

