

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIP DATE*
(Other instruction
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 032579(e)

6. INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME Prod. Lease
2. NAME OF OPERATOR Westates Petroleum Company	8. FIRM OR LEASE NAME Carlson B 26
3. ADDRESS OF OPERATOR Box 33, Jal. New Mexico	9. WELL NO. 5
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 2310' ^{FSL} FE 330' ^{FEL} FE Sec. 26, 25S 37E.	10. FIELD AND POOL, OR WILDCAT Justin
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 26-25S-37E
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3057' G. Level	12. COUNTY OR PARISH Lea
	13. STATE N. Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recombination Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1-11-71 - We propose to set Baker Cast iron plug at 5580' with cement cap. To temporary abandon Tubbs zone perfs. at 5764'-76'; 5794'-5804'. Run 3" frac tubing with Baker retrievable. Packer set at approx. 5025'. Frac Hlinebry zone with perfs. 5054'-94'; 5131'-38'; 5218; 5243'; 5259'; 5302'; 5325'; 5340'; 5347'; 5348'; 5388'. Frac with 30,000 gal. gelled brine water with 60,000 lbs. 20-40 sand. Swab and put well back on production as a Hlinebry well only.

18. I hereby certify that the foregoing is true and correct

SIGNED

W. F. Strull

TITLE

Prod. Supt.

DATE

12-31-70

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED
JAN 4 1971
ARTHUR A. CROWIN
FOR

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1965 O-348-229
507-851

SUNDRY NOTICES AND REPORTS ON WELLS

CALIFORNIA SURVEY

DEPARTMENT OF THE INTERIOR

UNITED STATES

RECEIVED

JAN 6 1971

U.S. DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT