

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TWO
(Other instruct.
verse side)DATE
re-Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 032579(6)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Federal Lease

8. FARM OR LEASE NAME

Carlson B 25

9. WELL NO.

5

10. FIELD AND POOL, OR WILDCAT

Harris Tubbs Park - Hlinebry

11. SEC. T. R. M., OR BLM. AND
SURVEY OR AREA

26-35S-37E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3054 Ground Level

12. COUNTY OR PARISH

Lea

13. STATE

New Mexico

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

7" casing 23# set 56249' Hlinebry Perfs. 5054' to 5138' Set bridge plug 5175'. Full bore packer 55010' Acidized Hlinebry zone w/10,000 gal. Super X 28% in two stages, with salt plug between stages overflushed each stage w/5000 gal. 3% acid. Swab back acid water. Pull fullbore packer and bridge plug.

Run tubing Tubbs string w/bridge plug and fullbore packer, set bridge plug 55835', fullbore packer 55730' acidized Tubbs zone perfs. 57843-5804' with 7500 gal. Super X acid 28%. Overflushed w/7500 gal. 3% acid. Swabbed back acid water, pulled bridge plug and fullbore packer. Run both strings of tubing. Set Baker lockset packer 55706' parallel string anchor at 5676'. Run rods, put well on pump.

18. I hereby certify that the foregoing is true and correct

SIGNED

W. J. Still

TITLE Production Superintendents

DATE April 14, 1967

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 7: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.