Form 3160-5 (July 1989) (Formerly 9-331) CONTACT RECEIVING OFFICE FOR NUMBER OF COPIES REQUIRED

BLM Roswell District Modified Form No. NM060-3160-4

UNITED STATES DEPARTMENT OF THE INTERIOR (Other instructions on reverse 5. LEASE DESIGNATION AND SERIAL NO. BUREAU OF LAND MANAGEMENT LC 0325791

SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals.)						6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
OIL GAS OTHER						7. UNIT AGREEMENT NAME		
2. NAME OF OPERATOR						8. FARM OR LEASE NAME		
MERIDIAN OIL INC						CARLSON HARRISON FED COM		
3. ADDRESS OF OPERATOR 3a. AREA CODE & PHONE NO.						9. WELL NO.		
P.O. Box 51810, Midland, TX 79710–1810 (915)688–6943						2		
 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) 						10. FIELD AND POOL, OR WILDCAT		
At surface D. 6602 ENI. 9.6602 ENI.					}	JALMAT TANSILL-YATES-7RV 11. SEC., T., R., M., OR BLK, AND		
D, 660' FNL & 660' FWL						SURVEY OR AREA		
						SEC 27, T255	6, R37E	
14. PERMIT NO.		15. ELEVATIONS (Show w	hether DF, R1	, GR, etc.)		12. COUNTY OR PARISH	13. STATE	
		3048 GR	.,			LEA	NM	
16.	Check App	propriate Box To In	ndicate N	ature of Notice, Re	eport,	, or Other Data		
NOTICE OF INTENTION TO: SUBSEQUE						ENT REPORT OF:		
TEST WATE	R SHUT-OFF PI	JLL OR ALTER CASING	7	WATER SHUT-OFF		REPAIRING W	/E	
FRACTURE TREAT		MULTIPLE COMPLETE		FRACTURE TREATMENT	X	ALTERING CASING		
SHOOT OR ACIDIZE		BANDON*		SHOOTING OR ACIDIZING		X ABANDONMENT*		
REPAIR WEL	.L cı	HANGE PLANS	4	(Other)			🗆	
(Other)	ROPOSED OR COMPLETED OPER		<u>.</u>	Completion or Re	ecomple	multiple completion or tion Report and Log fo	m.)	
work.)*	vork. If well is directionally of	frilled, give subsurface loca	ations and m	easured and true vertical d	epths fo	or all markers and zon	es pertinent to this	
9/24/91	KILL WELL.							
9/25/91 RIH W/ BIT, SCRAPER AND TBG. TAGGED @ 3052'. SET PKR @ 2687'. UNABLE TO PRESS UP. WELL CIRC OUT BRAIDEN HEAD.							P. WELL	
9/26/91 ISOLATE CASING LEAK BETWEEN 454-485'. PUMP 150 SXS CLASS "C" CMT. OBTAIN 500# BRAIDEN HEAD, SQUEEZE.							RAIDEN	
9/27/91	RIH W BIT. DRILL OUT CMT.							
9/28/91	1 TST SQUEEZE, OK.							
9/29/91	ACIDIZE PERFS 2765-3040' W/ 3000 GALS 7 1/2% HCL ACID.							
10/01/91	1/91 FRAC PERFS 2675-3040' W/ 123000# 12/20 BRADY SAND.							
10/02/91	/91 CO WELLBORE TO 3140'. CIRC HOLE CLEAN.							
10/03/91 RIH W/ TBG & TAG @ 3140'. PU TO 2742'. RIH W 2 1/2" X 1 1 /4" X 12' PUMP.								
10/03/91	TURN TO PRODUCTION.						19	
					PP 0 ~ 1002			
8. I hereby ce	rtify that the foregoing is true	and correct		PRODUCTION ASST			3/31/92	
	for Federal or State office us	1112		A.R.	SSA			

*See Instructions on Reverse Side

DATE

TITLE

CONDITIONS OF APPROVAL, IF ANY: