STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

JIGI MIO WILLIAM CO.		
we. er Contes Acceives		
DISTRIBUTION		
SANTA FE	Ι	
FILE		
U.\$.G.\$.		I
LAND OFFICE	_l	
OPENATOR		ł

OIL CONSERVATION DIVISION

Form C-103

0.15	THIBUTION		P. ∰. BOX				Kenizea in.	-1-73
SANTA	FE.	SANT	'A FE, NEW	MEXICO 87501	٦	5a. Indicate Type	of Leaso	
FILE						State	Fon	хx
U.\$.G.\$	·					5. State Oil & Go		
LANO C						5, State Off & Go	is Lease No.	
OPENA	TON						~~~~	·~
			SCOOLE ON	WELLS				
	SUNDRY OF USE THIS FORM FOR PROPERTY OF THE STATE OF THE	NOTICES AND F	SEPUKISUN	TICLES	١. }			TT
(DO H	USE "APPLICATIO	N FOR PERMIT -" (FOR	M C+101) FOR SUCH	PROPOSACS.7		7. Unit Agreemer	it Name	
1.						Nancy/Co	m #2	
01L WELL [] well XX	OTHER-				8. Form or Lease		
2. Name of Op	perator					(Cost	±	
Lovi	s B. Burleson,	Inc.				9. Well No.	7	
3. Address of	Operator					3, wen non	2	
		Midland.	Texas 7	9702		10, Field and Pa	al as Wildows	
	. Box 2479		**		1	()	_	
4. Location o	^	1000	East	- LINE AND 660	FEET FROM	pelme	st	 -
UNIT LET	TER	1900 FEET FROM	THE	LINE AND	7221 1	ZXIIIII		1111;
				. 27 E			/////////	
Sout	h	· 28 то	WHSHIP 25-5	37-E	NMPM.			1111.
						12. County	MILLE	UL.
TITITI				DF, RT, GR, etc.)		T 0.3		1111
		300)1' GR			Lea		7777
16.	Million Charles	prespriate Box	To Indicate N	ature of Notice, Repo	ore or Oth	er Data		
	Check A	ppropriate Dox	10 marene 2	SUB:	SEQUENT	REPORT OF	:	
	NOTICE OF IN	TENTION TO:						
				REMEDIAL WORK	\Box	ALTE	RING CASING	
PERFORM REA	MEDIAL WORK	PLUG	AND ABANDON		Ħ	PLUG	AND ABANDONMEN	NT XX
TEMPORARILY	ABANDON		_	COMMENCE DRILLING OPHS.				
PULL OR ALT		CHANG	E PLANS	CASING TEST AND CEMENT J	48 []			[
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				OTHER				
OTHER			<u></u>					
VIAL				il in annient date	e including	estimated date o	f starting any pr	oposea
17. Describe	Proposed or Completed Op-	erations (Clearly stat	e all pertinent det	ails, and give pertinent date				•
work) SE	EE RULE 1103.					•		
1.	Set cement re	tainer at 2	481.					
1)	Set cement re-	cainer ac 2	552 with	130 sx. class (ceme	nt		
	Squeezea peri:	5 al 2300-2	inor					
	Put 10 sx on	cob or reca	THET					
	_							
2)	Set 25 sx plug	g at 1217'						
				1 - 11 - 3 mamban				
3)	Set 10 sx plu	g at surfac	e and ins	talled marker				
,								
4)	Cleaned locat	ion						
- /								
						•		
		<u> </u>						
	Formerly	(lak #1						
	Overnery							
	C		•					
18. I hereby	certify that the information	above is true and co	mplete to the best	of my knowledge and belief	•			
ŕ	V. V.						2/24/22	
	Manny De	lairer)	TITLE DI	coduction Clerk		DATE	3/31/88	
#16HE0	ANIMONIO A	~m~~						-
	1	11	OTI	& GAS INSPEA	いこの氏	nfr.	1 2 1989	1
	\(\lambda \)	11 //	₩	~ ~ ~ ~ · · · · · · · · · · · · · · · ·			- ~ IUUU	,

