DA&S OIL WELL SERVICING

INCORPORATED

Lewis B. Burleson Sanders Estate No. 2

8/11/94 Move in, rig up, pick up and run tubing to 2,344', spot 150 sacks cement, pull tubing, shut down.

8/12/94 Run tubing in hole, tag cement at 1,844', circulate mud, pull and lay down tubing to 950', spot 35 sacks cement, pull tubing to 50', circulate 20 sacks cement to surface, cut off wellhead, put in marker, rig down, move off.

Class "C" Cement Mud 25 lb. Salt Gel per BBL.

OK By Charlie Perrin O.C.D.

505 392 6591

P.O. BOX 2545

HOBBS, NEW MEXICO 88241

MINERS OF WEART PORT BEST WAY.

MIDITAGO (EXAS PEDE) (BES BESE) FURILL LEM MERCO (BEE) (BES BESE)