DA&S OIL WELL SERVICING

INCORPORATED

Lewis B. Burleson, Inc. Gutman No. 1

- 9/13/94 Move in, rig up, lay down rods, put on BOP, pull and tally tubing, run bit and scraper to 2,500', shut down.
- 9/14/94 Pull out bit and scraper, run 7" cast iron bridge plug and set at 2,500', circulate mud, spot 25 sacks on top of cast iron bridge plug from 2,500' - 2,350', pull tubing to 1,000', spot 25 sacks from 1,000' - 650', pull to 30', circulate to surface, cut off wellhead, put in marker, rig down, move off.

Class "C" Cement Mud - 25 lb. Salt Gel per bbl.

505-392-6591 • P.O. BOX 2545 • HOBBS, NEW MEXICO 88241

FFC. - JED

SEP 2 8 1894

الله المحلومة الصحير المساول ا المساول المساول