

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No. NMJ 584	
7. Unit Agreement Name	
8. Farm or Lease Name JENKINS	
9. Well No. 3	
10. Field and Pool, or Wildcat Langlie Mattix	
12. County Lea	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator
TEXAS PACIFIC OIL CO., INC.

Address of Operator
P. O. Box 1069 - Hobbs, New Mexico 88240

Location of Well
UNIT LETTER **N** **760** FEET FROM THE **South** LINE AND **1980** FEET FROM
THE **West** LINE, SECTION **29** TOWNSHIP **25-S** RANGE **37-E** NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
3016' GR

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rigged up, pulled tubing (96 jts. 2-1/2" 6.5# 8 rd J-55 EUE)
2. Ram tubing w/CIBP @ 3040'.
3. Displaced well fluids w/mud laden fluid and spotted 15 sks. cement on plug.
4. Pulled tubing, spotted 10 sks. cement at surface.
5. Cut off well head and capped w/cement.
6. Set dry hole marker cut dead men and cleaned location ready for inspection.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signed by Sheldon Ward TITLE Area Superintendent DATE 7-15-71

APPROVED BY Nathan E. Clegg TITLE OIL & GAS INSPECTOR DATE DEC 7 1971

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JUL 15 1971

**OIL CONSERVATION COMM.
HOBBS, N. M.**