

NO. OF COPIES RECEIVED		
DISTRIBUTION		
ANTA FE		
ILE		
.S.G.S.		
AND OFFICE		
PERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
NMJ 584	
7. Unit Agreement Name	
8. Farm or Lease Name	
Jenkins	
9. Well No.	
3	
10. Field and Pool, or Wildcat	
Jailanglie Mattix	
12. County	
Lea	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER- ☐

Name of Operator
TEXAS PACIFIC OIL CO., INC.

Address of Operator
P. O. Box 1069 - Hobbs, New Mexico 88240

Location of Well
UNIT LETTER **N** **760** FEET FROM THE **South** LINE AND **1980** FEET FROM
THE **West** LINE, SECTION **29** TOWNSHIP **25-S** RANGE **37-E** NMPM.


15. Elevation (Show whether DF, RT, GR, etc.)
3016' GR

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
ILL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig up and pull tubing.
2. Run buging with CIBP and set @ 3040'.
3. Displace well fluids with mud laden fluid and spot 15 sks. cement top CIBP. Pull Tbg.
4. Spot 10 sks. cement at surface.
5. Cut off well head and cap with cement.
6. Set dry hole marker cut dead men and clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

ED	TITLE	DATE
	Area Superintendent	5-14-71
ROVED BY	SUPERVISOR DISTRICT	DATE
		MAY 17 1971
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

MAY 1 1971

OIL CONSERVATION COMM.
HOBBS, N. M.