

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No. NMJ 580
7. Unit Agreement Name
8. Farm or Lease Name DYER
9. Well No. 1
10. Field and Pool, or Wildcat Jalmat Oil
12. County Lea

SUNDY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>
2. Name of Operator TEXAS PACIFIC OIL CO., INC.
3. Address of Operator P. O. Box 1069 - Hobbs, New Mexico 88240
4. Location of Well UNIT LETTER B , 330 FEET FROM THE North LINE AND 2310 FEET FROM THE East LINE, SECTION 31 TOWNSHIP 25-S RANGE 37-E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3002' GR

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK	<input type="checkbox"/>
TEMPORARILY ABANDON	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>
OTHER	<input type="checkbox"/>

PLUG AND ABANDON	<input checked="" type="checkbox"/>
CHANGE PLANS	<input type="checkbox"/>
OTHER	<input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK	<input type="checkbox"/>
COMMENCE DRILLING OPNS.	<input type="checkbox"/>
CASING TEST AND CEMENT JOB	<input type="checkbox"/>
OTHER	<input type="checkbox"/>
ALTERING CASING	<input type="checkbox"/>
PLUG AND ABANDONMENT	<input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRU. Pull tubing. Set CIBP @ 3080'.
2. Displace well fluids w/mud laden fluid, spot 35 sk cement on top of CIBP.
3. Spot 10 sk Cement plug at surface.
4. Cut off wellhead and cap w/cement. Install dry hole marker.
5. Clean location.

*10' plug @ top 30 ft
24 hrs in time*

ILLEGIBLE

18. I hereby certify that the information above is true and complete to the best of my kn

Original Signed by

SIGNED C. R. Tilley

TITLE Area Production Foreman

DATE 7-25-73

Orig. Signed by
Joe D. Ramey
Dist. I, Supv.

APPROVED BY _____

TITLE _____

DATE 7-25-73

CONDITIONS OF APPROVAL, IF ANY: