ENERGY AND MINERALS DEPARTMENT

DISTRIBUTION	1	ī
SANTA PE	_	
FILE	†	
U.S.G.S.	1	
LAND OFFICE	 	
OPERATOR	 	

INDITIONS OF APPROVAL, IF ANY

OIL CONSERVATION DIVISION P. O. BOX 2088 SANTA FE, NEW MEXICO 87501

Form C-103 Revised 19-1-78

.... DEC 9 1983

U.S.O.S.	So Indiana T
LAND OFFICE	5a. Indicate Type of Leuse
OPERATOR	State Fee
	S. State Oil & Gas Lease No. Patented
SUNDRY NOTICES AND REPORTS ON WELLS	racenced
SUNDRY NOTICES AND REPORTS ON WELLS 100 HOT USE THIS FORM FOR PROPOSALS TO DRILL ON TO GEEPEN OF PLUG BACK TO A DIFFERENT RESERVOIR. 1.	
01L (V)	
WELL X GAB WELL OTHER-	7. Unit Agreement Name
	9 5
Sun Exploration & Production Co. 3. Address of Operator	M. F. Legal
P. O. Box 1861, Midland, TX 79702	9. Well No.
4. Location of Well	2
	10. Field and Pool, or Wildcat
UNIT LETTER I 1980 FEET FROM THE SOUTH LINE AND 660 FEET FROM	151 mat
Fact Of	Jalmat
THE East LINE, SECTION 31 TOWNSHIP 25-S RANGE 37-E	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
2996' GR	
Check Appropriate Box To Indicate Nature of Notice, Report or Ot	260
NOTICE OF INTENTION TO:	ner Data T REPORT OF:
	REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	. —
TEM. JRARILY ABANDON	ALTERING CASING
CHANGE PLANS CASING TEST AND CEMENT JOB	PLUG AND ABANDONMENT
o _{ther} Continued Compl	etion to previously
Submitted C-103	on 9/27/83 to deepon
7. Describe Proposed or Completed Operations (Clearly state all perspect described to the Complete as O	il producer
work) SEE RULE 1103.	estimated date of starting any proposed
Submitted C-103 for allowable purposes 9/27/83. This is continued co	
purposes 9/27/65. Inis is continued co	ompletion.
10/27 MIRU Pool WS nob w/ rode & non Alb. 33 4	
10/27 MIRU Pool WS, poh w/ rods & pmp, ND well head, NU BOP. POH w, Plug back w/ SD from 3210-3100.	/ 2-3/8 prod set up.
10/28 Perf Jalmat set V perfs 3070-88 2 JSPF, 37 holes. Set Pkr @ 2500 psi ok. Howco acdz Jalmat set V perfs 3070-88 w/ 500 gals 15% No	
500 psi ok. Howco acdz Jalmat set V perfs 3070-88 w/ 500 rals 158	2942, press annulus to
500 psi ok. Howco acdz Jalmat set V perfs 3070-88 g JSPF, 37 holes. Set Pkr @ 2 sealers in one stage.	FE HCL & 55 ball
10/29 FL 1500-2850 stabilized, good show gas. (Stabalized @ 2850)	
10/20 Fig. 17	
10/30 Frac Jalmat Set V perfs 3070-3088 down 2-3/8 tbg w/ 10,000 gal gel & 17,500# 20/40 sd, preceed by 2500 gals pad in one stage	C min way III
gel & 17,500# 20/40 sd, preceed by 2500 gals pad in one stage.	s min-max 111 - 30
11/1 Swab, small show gas. RIH cln out to PBTD.	
	•
11/2 Cln out SD 3119 to 3210 PBTD. RIH w/ 2-3/8 prod set up, TS 319 2 x $1\frac{1}{4}$ x 12' pmp & rods.	92. SN 3156 PTH/
	on 0100, kill w/
11/16 24 Hrs, P, 6 BO, 65 BW, 97 MCF, GOR 16,166/1	•
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	<u> </u>
$M \cdot I O$	
Name Line Senior Accounting Assistant	10/5/5
OBIGINAL COLOR OF THE SERVICE MECOUNTING ASSISTANT	DAYE 12/5/83
ORIGINAL SIGNED BY EDDIE SEAY	
OIL & GAS INSPECTOR	DEC 0 1000
	116.13 11 7 000