

SERVICE WORK PROCEDURE

WELL DATA:

LEASE AND WELL Gregory A #2 DATE 10-18-82

FIELD AND RESV.	DATE
Langley-Matrix (7-Runs Queen Grayburg)	10-10-85

PROBLEM, CAUSE, SOLUTION, AND RECOMMENDATION Well has been TAD
SINCE 1962. US Dept of Interior requests testing
of CGG

CASING DATA 5-1/2" 15.5# PBD _____ TD 3174

LINER DATA _____

PERFS OK 3051-2174

TUBING DATA

PACKER OR DOWNHOLE TOOL DATA

PRESENT PRODUCTION AND METHOD

MISC. INFORMATION Contact NEDT office in Hobbs to have
representative witness sent. Telephone # (505) 393-3612

PROCEDURE:

- 1) MDPH w/ rig, PCH w/ rods. Install REP, PCH w/ 4kg.
- 2) PCH w/ bit & CSG scraper on 2-3/4" WS. CO to let to CS.
- 3) PCH w/ WS, bit and scraper.
- 4) PCH w/ REP, PDC skt on WS.
- 5) Set REP at 3020', Set pkr at 2970'. Test REP to 500 psi.
- 6) Raise skt and load annulus w/ inhibited produced water.
- 7) Test rep to 500 psi.
- 8) If leak is found, isolate by moving pkr to various depths.
- 9) PCH w/ WS, skt and REP. SI.
- 10) _____
- 11) _____
- 12) 1/2 in Inhibit water and 1/2 gal / (100 lb) KW-79

ORIGINATOR: _____ AREA ENG _____ SUPT. _____

RECEIVED

SEP 19 1984

U.S. DEPT. OF JUSTICE
HONORABLE OFFICE