

Form 3160-5  
(July 1989)  
(Formerly 9-331)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

BLM CARLSBAD

CONTACT RECEIVING  
OFFICE FOR NUMBER  
OF COPIES REQUIRED  
(Other instructions on reverse  
side)

BLM Roswell District  
Modified Form No.  
NM060-3160-4

5. LEASE DESIGNATION AND SERIAL NO.  
LC-054667

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT-" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Meridian Oil Inc.

3. ADDRESS OF OPERATOR

21 Desta Dr., Midland, TX 79705

3a. AREA CODE & PHONE NO.

915-686-5678

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)

At surface

660' FSL & 990' FEL

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Gregory "A"

9. WELL NO.

6

10. FIELD AND POOL, OR WILDCAT

Langlie-Mattix (7R, Q, GB)

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 33, T25S, R37E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3007' DF

12. COUNTY OR PARISH

Lea

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

SUBSEQUENT REPORT OF:

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Retainer set @2387'--discovered holes @1048', 402'-463', and 0-25'.

Reconfirm location of holes using a cup-type packer. If the holes are as reported, the well will be plugged and abandoned using the following procedure.

Class "C" cement + 2% CaCl<sub>2</sub> plugs will be placed as follows:

1. 50 sx below retainer @2387'.

2. 20 sx on top of retainer @2387'.

3. Set retainer @950' and put 50 sx below retainer, AND 50' ABOVE RETAINER.

4. ~~Circulate 70 sx to surface.~~ SET 100' CEMENT PLUG FROM 308'-208', TAG PLUG  
Install a dryhole marker and ~~clean up location.~~ SPOT 50' CEMENT SURFACE PLUG,  
RESTORE

PLEASE: NOTIFY BLM AT (505) 393-3612 PRIOR TO  
COMMENCING PLUGGING OPERATION.

PLACE MUD OF A MINIMUM WEIGHT OF 9 PPg  
BETWEEN PLUGS.

18. I hereby certify that the foregoing is true and correct

SIGNED

*Robert L. Bradshaw*

TITLE

Sr. Staff Env./Reg. Spec.

DATE

11 October 1990

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

11-20-90

\*See Instructions on Reverse Side