

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

Lease Designation and Serial No.
LC-032510 B

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

If Indian, Aneechee or Tribe Name

If Unit or C.A. Agreement Designation

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Meridian Oil Inc.

3. Address and Telephone No.

P.O. Box 51810, Midland, TX 79710-1810 915-683-6800

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1980' FNL & 660' FEL
Sec. 35, T25S, R37E

5. Well Name and No.

Gregory C #2

6. API Well No.

20 25 18 15

7. Field and Pool, or Exploratory Area

Langlie Mattix

8. County or Parish, State

Lea

CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☒ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

☐ Dispose Water

Note: Report results of multiple completion on well completion or Recompletion Report and Log form.

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

12/23/92 Notified BLM - MIRU. W.H w/stinger on tbq. Set cmt retainer @3175'. Spot 25 sxs cmt. below retainer & 10 sxs above. Pull tbq. up to 3260'. Spot 25 sxs cmt. Pull tbq. up to 1260'. Spot 26 sxs cmt. Pull tbq. out of hole. Removed stinger. SDFN.

12/24/92 Opened well up. Removed BOP. Cmt. 40 sxs cmt. to surf. Pull tbq. out of hole RDMO. Cap well and install dry hole marker.

14. I hereby certify that the foregoing is true and correct

Signed

Title

Production Assistant

Date

1-6-92

(This space for Federal or State office use)

Approved by

Title

Date

1-19-93

Conditions of approval, if any:

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

5. Lease Designation and Serial No.
LC-032510-B

6. Indian, Alutotie or Tribe Name

7. Unit or CA Agreement Designation

SUBMIT IN TRIPLICATE

1. Type of Well
☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Meridian Oil Inc.

3. Address and Telephone No.

P.O. Box 51810, Midland, TX 79710

915-688-6800

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1980 FNL & 660 FEL

Sec. 35 T-25-S, & R-37-E

8. Well Name and No.

Gregory C #2

9. API Well No.

10. Field and Pool, or Exploratory Area

Langlie Mattix

11. County or Parish, State

Lea

CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Notify Hobbs BLM Office prior to starting work. MIRU PU. ND wellhead, NU BOP. Deliver workstring to location. PU workstring, RIH, and sting into retainer at 3175'. Retainer was set in 1990 by Schlumberger and is believed to an Elder retainer. Establish pump-in rate under retainer and squeeze open hole with 25 sxs cement. Sting out of retainer and spt 10 sxs of cement on top of retainer. Pull up above plug and circulate hole with 9 ppg gelled brine.
2. Pull up to 2260' and set a cement plug across the base of the salt at 2140' to 2260' using 15 sxs of cement. Pull up to 1260' and set a cement plug across the top of the salt at 1140' to 1260' using 15 sxs of cement. Pull up to 380' and circulate cement to surface using 40 sxs of cement. POOH laying down tubing. RDMO PU. Cut off casing 3' below GL and install P & A monument. Clear, rip and reseed location.

14. I hereby certify that the foregoing is true and correct

Signed

Title **Production Assistant**

Date **12-7-92**

(This space for Federal or State office use)

Approved by

Title

Date

Conditions of approval, if any: