

SERVICE WORK PROCEDURE

WELL DATA:

LEASE AND WELL L. L. Gregory #1 DATE 10-16-83
 FIELD AND RESV. Langlie-Matrix (H. River Queen Grayburg)
 PROBLEM, CAUSE, SOLUTION, AND RECOMMENDATION Well has been TA'd since 1975. US Dept of Interior requests testing of CSG.

CASING DATA 5-1/2", 15.5 # PBD TD 3284'

LINER DATA

PERFS OH 3050-3284'

TUBING DATA

PACKER OR DOWNHOLE TOOL DATA

PRESENT PRODUCTION AND METHOD

MISC. INFORMATION Contact UEDT office in Hobbs to have representative witness test. Telephone # (505) 393-3612.

PROCEDURE:

- 1) MDRILL W/O rig. POH w/ rods. Install BOP. POH w/ tbg
- 2) R/L w/ bit and csg scraper ON 2-3/8" WS. CO hole to CS.
- 3) POH w/ WS, bit and scraper.
- 4) R/L w/ REP, RTG pkr ON WS.
- 5) Set REP at 3020'. Set pkr at 2970'. Test REP to 500 psi.
- 6) R/L pkr and load annulus w/ inhibited produced water.
- 7) Test csg to 500 psi.
- 8) If leak is found, isolate by moving pkr to various depths.
- 9) POH w/ WS, pkr and REP SI.
- 10)
- 11)
- 12) Note: Inhibit water w/ 10 gal/100 bbl KW-79

ORIGINATOR: David J. J. J. AREA ENG. SUPT.