Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

District Office	Ellergy, Millerais and Natural	•	Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobbs NM 88240	OIL CONSERVATION DIVISION P.O. Box 2088 Santa Fe, New Mexico 87504-2088		WELL API NO. 30-025-11901
DISTRICT II P.O. Drawer DD, Artesia, NM 88210			5. Indicate Type of Lease
DISTRICT III			STATE X FEE 6. State Oil & Gas Lease No.
1000 Rio Brazos Rd., Aztec, NM 87410			B-229
	FICES AND REPORTS ON WE OPOSALS TO DRILL OR TO DEEPEN		
DIFFERENT RESE (FORM C	ERVOIR, USE "APPLICATION FOR PE C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name SOUTH JUSTIS UNIT "G"
1. Type of Well: OIL WELL GAS WELL WELL] OTHER		
2. Name of Operator			8. Well No.
ARCO Permian 3. Address of Operator			9. Pool name or Wildcat
P.O.BOX 1610, MIDLAND,	TX 79702		JUSTIS BLBRY-TUBB-DKRD
4. Well Location Unit Letter G : 1980	Feet From The NORTH	Line and 1980	Feet From The EAST Line
Section 36	Township 25S	Range 37E	NMPM LEA County
	10. Elevation (Show when 3034 GR	her DF, RKB, RT, GR, et	(c.)
ERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
EMPORARILY ABANDON	PLUG AND ABANDON CHANGE PLANS	COMMENCE DRILLING	G OPNS. PLUG AND ABANDONMENT
work) SEE RULE 1103. 11-10-95. RUPU. POH W/	PROD CA. RIH W/4 3/4 BW/1000 GALS. RIH W/PRO	COMMENCE DRILLING CASING TEST AND COMMENCE DEEPEN OTHER: DEEPEN etails, and give pertinent da IT TO 5915. DO S	B-T-D TO 6100 & TREAT Tates, including estimated date of starting any proposed SHOE F/5915-16. DNF F5916-6100.
PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Orwork) SEE RULE 1103. 11-10-95. RUPU. POH W/I ACIDIZED OH 5916-6100 M	perations (Clearly state all pertinent dependence) PROD CA. RIH W/4 3/4 BW/1000 GALS. RIH W/PRO	COMMENCE DRILLING CASING TEST AND CE OTHER: DEEPEN etails, and give pertinent de IT TO 5915. DO S D CA:2 3/8 TBG, R	B-T-D TO 6100 & TREAT Tates, including estimated date of starting any proposed SHOE F/5915-16. DNF F5916-6100.
TEMPORARILY ABANDON PULL OR ALTER CASING DTHER: 12. Describe Proposed or Completed Orwork) SEE RULE 1103. 11-10-95. RUPU. POH W/ACIDIZED OH 5916-6100 B-T-D PROD INTERVAL 4	perations (Clearly state all pertinent dependence) PROD CA. RIH W/4 3/4 BW/1000 GALS. RIH W/PROD Strue and complete to the best of my knowled the structure.	COMMENCE DRILLING CASING TEST AND CE OTHER: DEEPEN etails, and give pertinent de IT TO 5915. DO S D CA:2 3/8 TBG, R	B-T-D TO 6100 & TREAT Ates, including estimated date of starting any proposed SHOE F/5915-16. DNF F5916-6100. RODS & PUMP TO 6045. RDPU 11-20-

TITLE _

APPROVED BY CONDITIONS OF APPROVAL, IF ANY: