SANTA FE, NEW MEXICO

MISCELLANEOUS NOTICES Suffinite his hotice intriplicate to the Oil Conservation Commission or its proper agent before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed and work should not begin until approval is obtained. See additional instructions in the Rules and Resembles of

advisable, or the rejection by the Commission of agent, of the plan submitted. The plan as approved should not begin until approval is obtained. See additional instructions in the Rules and Residual of the Commission: Indicate nature of notice by checking below:		
Indicate nature of notice	e by checking below:	
NOTICE OF INTENTION TO TEST CASING SHUT-OFF 7"	NOTICE OF INTENTION TO SHOOT OR CHEMICALLY TREAT WELL	1
NOTICE OF INTENTION TO CHANGE PLANS	NOTICE OF INTENTION TO PULL OR OTHERWISE ALTER CASING	
NOTICE OF INTENTION TO REPAIR WELL	NOTICE OF INTENTION TO PLUG WELL	
NOTICE OF INTENTION TO DEEPEN WELL		
honbs. Ne	w Mexico 1/a 7, 1951	
	Place Date	
OIL CONSERVATION COMMISSION, Santa Fe, New Mexico		
Gentlemen:		
Following is a notice of intention to do certain work as descr		
Company or Operator Company or Operator Lease	Well No3	
of Sec. 36 T 25 S R 37 E N	M. P. M. Stylie-Battix	Field
County,	DOCED DI AN GE WORK	
FULL DETAILS OF PROP	OSED PLAN OF WORK	
on May 5, 1951, ran 98 joints. 3147'. So casing with short T&C. Set and demente	ed at 3148; with 265 s rolk 2	
on May 5, 1951, ran 98 joints. 3147' SJ casing with short T&C. Set and cemente Jel neg. cement. Thug at 3114. Job comproses to drill plug and test saut-o	g of 7% OD 20g f 2.92 k-40 net ed at 3148; with 265 s the kolk 2; glete at 1:30 May 5 1,51. off 1:30 May 7, 1951.	
on May 5, 1751, ran 98 joints. 3147'; So casing with short T&C. Set and cemente Jed Aeg. cement. Ting at 3114 . Job com	g of 7% OD 20g f 2.92 k-40 net ed at 3148; with 265 s the kolk 2; glete at 1:30 May 5 1,51. off 1:30 May 7, 1951.	É
On May 5, 1951, ran 98 joints, 31471 So casing with short T&C. Set and cemente Jed deg. cement. Tug at 3114. Job com Promose to drill plug and test shut-of	g of 7% OD 20g f 2.92 k-40 net ed at 3148; with 265 s the kolk 2; glete at 1:30 May 5 1,51. off 1:30 May 7, 1951.	É
On May 5, 1951, ran 98 joints, 31471 So casing with short T&C. Set and cemente Jed deg. cement. Tug at 3114. Job com Promose to drill plug and test shut-of	of 7% OD 20g f 2.72 -40 net ed at 3148% with 265 s . 3 kulk 2; nete at 1:30	
On May 5, 1951, ran 98 joints, 31471 SU casing with short T&C. Set and cemente Jed deg. cement. Tug at 3114. Job com Promose to drill plug and test saut- Approved	of 7" OD 20g f 1.22 -40 net ed at 3148' with 265 s . 2 kulk 2; hete at 1:30	well to
On May 5, 1951, ran 98 joints, 31471 So casing with short T&C. Set and cemente Jed deg. cement. Tug at 3114. Job com Promose to drill plug and test saut- Approved	of 7% OD 20% f A.T2 A-40 net ed at 3148 with 265 s as rolk 2. A 5 1.51. off 1:30 We 7, 1951. Company or Operator By Position Annual K. G. D. L. Send communications regarding	well to