STATE UP NEW MEXICU ENERGY AND MINERALS DEPARTMENT

FRGY AND MINEHALS DE	PAR	11410
DISTRIBUTION		
SANTA FE		<u> </u>
FILE	1_	
U.S.G.S.		
LAND OFFICE		↓
OPERATOR	ł	1

CONDITIONS OF APPROVAL, IF ANYI

OIL CO	NSERVATION DIVISION	Form C-103
DISTRIBUTION	P. O. BOX 2088	Revised 10-1-78
SANTA FE SANTA	A FE, NEW MEXICO 87501	
FILE		Sa. Indicate Type of Lease
v.s.g.s.		State X Fee
LAND OFFICE		5. State Off 6 Gas Lease No.
OPERATOR		В-228
SUNDRY NOTICES AND R	EPORTS ON WELLS	UIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII
COO NOT USE THIS FORM FOR PROPOSALS TO ORILL OR TO DO	TEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. 4 C-101) FOR SUCH PROPOSALS.)	2 Thus Agreement Name
		7. Unit Agreement Name
OIL TO SAN DOTHER		
MELL X MELL OTHER-		8. Farm or Lease Hame
2: Name of Operator Chevron U.S.A. Inc.	•	Vinson Ramsey NCT-B
Chevron U.S.A. The.		9. Weil No.
3. Address of Operator	20240	6
P.O. Box 670 Hobbs, NM 8	88240	10. Field and Pool, or Wildcat
4. Location of Well		Justis Blinebry
100A	South 1980	MON JUDETO BITHERTA
UNIT LETTER PEET FROM T		VIIIIIIIIIIIIIII
	25S 37E	WHIIIIIIIII
THE West LINE SECTION 36 TOW	NNSHIP 25S RANGE 37E	
ARE		12. County
: TTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTT	on (Show whether DF, RT, GR, etc.)	Lea
	3029 GL	
THILLIAN THE THE TANK	To Indicate Nature of Notice, Report or	· Other Data
Check Appropriate Box	charent	JENT REPORT OF:
NOTICE OF INTENTION TO:		
		ALTERING CASING
PLUG A	AND ABANDON REMEDIAL WORK	PLUG AND ABANDONMENT
PERFORM REMEDIAL WORK	COMMENCE DRILLING OPHS.	PLUE AND ASAHODHMENT
TEMPORABILY ASANDON CHANG	<u></u>	Plinaham Pariformi
PULL OR ALTER CASING	OTHER Add Additional	Blinebry Perforations x
QTHER		
17. Describe Proposed or Completed Operations (Clearly state	· all pertinent details, and give pertinent dates, inci	luding estimated date of starting any proposed
17. Describe Proposed or Completed Operations (Clearly stat.	-	/
work) SEE ROLE 11001	and amodustion tubing. RTH and	d run GR/CCL.
MIRU PU. POH with rods, pump,	and production tubing. Rin and production tubing.	5307 (13 holes).
Set CIBP @5345 and test at 50	of NEEL ICI Swabbed well. Fra	ac well with
Acidized well with 4000 gal 1	5% NEFE HCL. Swabbed well. Fra	red to pump.
46650 gals 40# X-Linked gel p	ad + 160150# 20-40 sand. Equipp	Land Lamba
Resume production.	•	•
vesame broadcriou.		
	·	
<u>.</u>		
•		
		_
	•	
	•	
18. I hereby certify that the information above is true and co	mplete to the best of my knowledge and belief.	
18. I hereby certify that the information above is true and co		
un, H		ineer 3/28/86
INWI ASUX	Division Proration Engi	Va.10
1 (CRED		W. O.
70:01- A		Jok 1 - 1986
ORIGINAL VIOLENCE CONTROLLAND	****	OATE
POSTO CONTRACTOR	T(TLE	