

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-11921
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-229
7. Lease Name or Unit Agreement Name SOUTH JUSTIS UNIT "E"
8. Well No. 29
9. Pool name or Wildcat JUSTIS BLBRY-TUBB-DKRD
10. Elevation (Show whether DF, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL GAS WELL OTHER

2. Name of Operator
ARCO Permian

3. Address of Operator
P.O. BOX 1610, MIDLAND, TX 79702

4. Well Location
Unit Letter **L** : **2310** Feet From The **SOUTH** Line and **990** Feet From The **WEST** Line
Section **36** Township **25S** Range **37E** NMPM **LEA** County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: DEEPEN B-T-D TO 6000 & TREAT <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-30-95. RUPU. POH W/PROD CA. RIH W/6 1/8 BIT TO 5870. CO JUNK F/5870-5899. DRILL OUT FLT SHOE F/5899-5900. DRILL NEW B-T-D FORMATION TO 6100 NEW TD. ACIDIZED OH 5900-6100 W/1000 GALS. RIH W/PROD CA:2 3/8 TBG,RODS & PUMP TO 6083. ROPU 11-09-95.

B-T-D PROD INTERVAL 5050-6100

I hereby certify that the information above is true and complete to the best of my knowledge and belief.
SIGNATURE Ken W. Gosnell TITLE AGENT DATE 11-14-95
TYPE OR PRINT NAME Ken W. Gosnell TELEPHONE NO. 915 688-5672

(This space for State Use)
APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: