

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30 025 12221
Indicate Type of Lease STATE ☐ FEE ☒
State Oil & Gas Lease No. NM-0349952
Lease Name or Unit Agreement Name West Dollardhide Drinkard Unit
Well No. 3
Pool name or Wildcat Dollardhide, Drinkard, Tubbs, Queen
Well Location Unit Letter <u>D</u> : <u>660</u> Feet From The <u>North</u> Line and <u>630</u> Feet From The <u>West</u> Line Section <u>19</u> Township <u>24S</u> Range <u>38E</u> NMPM <u>Lea</u> County Elevation (Show whether DF, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

Type of Well OIL WELL ☐ GAS WELL ☐ OTHER <u>Injector</u>
Name of Operator Texaco E&P Inc.
Address of Operator P.O. Box 3109, Midland, Texas 79702
Well Location Unit Letter <u>D</u> : <u>660</u> Feet From The <u>North</u> Line and <u>630</u> Feet From The <u>West</u> Line Section <u>19</u> Township <u>24S</u> Range <u>38E</u> NMPM <u>Lea</u> County Elevation (Show whether DF, RKB, RT, GR, etc.)

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ANBANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) Notify OCD of intent to plug
- 2) MIRU, NU BOP
- 3) Tag retainer @ 6510, mix and circulate 10# mud
- 4) Spot 20 sx cement fm 6188-6288 (Tubbs)
- 5) Spot 20 sx cement fm 5240-5340 (Glorieta)
- 40 6) Spot 20 sx cement fm 3577-3677 (Queen) 3577-3887 grayburg
- 7) Perf/Sqz 40 sx cement fm 3200-3300 (8 5/8 shoe) WOC/Tag
- 8) Perf/Sqz 40 sx cement fm 2658-2758 (b-salt) WOC/Tag
- 9) Perf/Sqz 40 sx cement fm 1240-1430 (t-salt) WOC/Tag
- 10) Perf/Sqz 60 sx cement fm 300-400 out 8 5/8 csg (13 3/8 shoe) WOC/Tag
- 11) Spot 5 sx cement fm 50'
- 12) RDMO, cut off well head, install dry hole marker, clean location

THE FOLLOWING IS A TRUE AND CORRECT COPY OF THE INFORMATION CONTAINED IN THE ORIGINAL FILED IN THE OFFICE OF THE CLERK OF THE DISTRICT COURT OF THE COUNTY OF LEA, NEW MEXICO, ON 12-01-99.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jim T. Corbitt TITLE Engineer DATE 12-01-99
TYPE OR PRINT NAME Jim Corbitt TELEPHONE NO. (915) 688-4438

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL (IF ANY)