

Submit 3 Copies To Appropriate District
Office

District I
1625 N. French Dr., Hobbs, NM 88240

District II
1301 W. Grand Avenue, Artesia, NM 88210

District III
1000 Rio Brazos Rd., Aztec, NM 87410

District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-12239
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Chevron USA, Inc. ✓		6. State Oil & Gas Lease No.
3. Address of Operator 15 Smith Rd. Midland, Tx 79705		7. Lease Name or Unit Agreement Name: West Dollarhide Drinkard Unit
4. Well Location Unit Letter <u>I</u> : 1980 feet from the <u>south</u> line and <u>660</u> feet from the <u>east</u> line Section <u>29</u> Township <u>24-S</u> Range <u>38-E</u> NMPM County <u>Lea</u>		8. Well No. 24
10. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. Pool name or Wildcat Dollarhide Drinkard Oil

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Tag 4 CIBP @ 6600 spot 50sx plug fr/6600-5990(Blinbry)TOL @ 6142 Tag @ 5959
2. Displace hole w/MLF 9.5 # Brine w/25 # Gel P/BBL.
3. Perf 4 holes @ 3800 unable to sqz spot 40sx plug fr/3850-3600(Queen) Tag @ 3380
4. Perf 4 holes @ 3200 unable to sqz spot 65sx fr/3250-2700(8 5/8 shoe, B-salt, Yates) Tag @ 2681
5. Perf 4 holes @ 1400 unable to sqz spot 30sx f4/1400-1200(T-salt) Tag @ 1187
6. Perf 4 holes @ 400 unable to sqz circ cmt fr/450 to surf w/50sx Tag @ surf
7. Install dry hole marker 11-25-02

Approved as to Plugging of the Well Bore.
Liability under bond is retained until
Surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE MANAGER/SUNSET

DATE 11-25-02

Type or print name

Jimmy BAGLEY

Telephone No. 915520-8752

(This space for State use)

ORIGINAL SIGNED BY
CHRIS WILLIAMS

APPROVED BY OC DISTRICT SUPERVISOR/GENERAL MANAGER

DATE

DEC 13 2002

Conditions of approval, if any: