	and the second s	•
NO. OF COPIES RECEIVED		Form C-103 Supersedes Old C-102 and C-103
SANTA FE	NEW MEXICO OIL CONSERVATION COMMIS	SION Effective 1-1-65
FILE		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
U.S.G.S.		5a. Indicate Type of Lease
LAND OFFICE		State 🗶 🛛 🛛 Fee
OPERATOR		5. State Oil & Gas Lease No.
	-	B-9519
(DO NOT USE THIS FORM FOR PR USE **APPLICA	RY NOTICES AND REPORTS ON WELLS oposals to drill or to deepen or plug back to a different re- tion for permit -" (form C-101) for such proposals.)	
1. OIL GAS WELL .	OTHER-	7. Unit Agreement Name West Dollarhide Drinkard Unit
2. Name of Operator		8, Farm or Lease Name
Skelly Oil Company 3. Address of Operator		West Dollarhide Drinkard Unit
P. 0. Box 1351, Mid	land, Texas 79701	23 i3. Field and Pool, or Wildcat
UNIT LETTERG, _10	80 FEET FROM THE North LINE AND 1980	Dellarhide Tubb-Drinkard
THE <b>East</b> Line, sect	ION 29 TOWNSHIP 245 RANGE 381	2 \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	3223' DF	Lea
	Appropriate Box To Indicate Nature of Notice,	Pepett on Other Data
		SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS CASING TEST AND CEN	the second
PULL OR ALTER CASING		c leak in 5-1/2" OD casing
OTHER		A ACON AN J-1/6 OD COOMING
		datas instruction assimpted date of starting any proposed

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well is producing from Drinkard perforations 6740' - 6760'. The following work was done to shut off water which began flowing outside 8-5/8" OD surface casing:

- 1) Moved in and rigged up pulling unit May 28, 1971. Pulled rods and tubing.
- 2) Set Halliburton retrievable bridge plug at 6079' and tested 5-1/2" OD casing to 1000#, tested OK.
- 3) Perforated 5-1/2" OD casing at 4050' and cemented through perforations with 750 sacks cement.
- 4) Temperature Survey indicated top of cement at 485' outside casing.
- 5) Drilled cement 3922' 4080'; tested casing to 1000#, held OK.
- 6) Retrieved bridge plug.
- 7) Ran rods and tubing and returned well to production status on June 3, 1971, with water flow outside 8-5/8" OD casing shut off.

In conversation with Lavonne Frye and John Runyan at 3:30 MDT June 11, 1971, it was explained that we inadvertently failed to notify the Commission before work was begun on this well due to misunderstanding within our organization. Please accept our apology for this omission.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

signed (Signed) J. R. Avent	TITLE Dist. Adm. Coordinator	DATE JUNE 14, 1971
APPROVED BY Les les fel Concents	DIL & GAS INSPECTOR	DATE JUN 17 1971
CONDITIONS OF APPROVAL, IF ANY:		

## RECEIVED

یں۔ بر ا

JUN 1 61971 į OIL CONSERVATION COMM. HOBBS, N. M.

.

rter s 1 m