	ġ.		
NO. OF COPIES RECEIVED	<b>.</b>		Form C-103 Supersedes Old
DISTRIBUTION			C-102 and C-103
	NEW MEXICO OIL CON		Effective 1-1-65
FILE	н. С		5a. Indicate Type of Lease
U.S.G.S.		001 3 1/ 29 M 20	State Fee.
OPERATOR			5. State Oil & Gas Lease No.
			•••
		WELLS	///////////////////////////////////////
DO NOT USE THIS FORM FOR PROP USE **APPLICATIO	Y NOTICES AND REPORTS ON posals to drill or to deepen or plug on for permit -" (form C-101) for su	A WELLS BACK TO A DIFFERENT RESERVOIR. CH PROPOSALS.)	λ////////////////////////////////////
1		· ·	7. Unit Agreement Name West Dollarhide Queen
OIL GAS WELL WELL	OTHER-	· -	Sand Unit
2. Name of Operator			8. Farm or Lease Name
Skelly Oil Company			
3. Address of Operator			9. Well No.
P. O. Box 730 - Hoh	bs, New Mexico 88240		10
4. Location of Well		2210	10. Field and Pool, or Wildcat Dollarhide Queen
UNIT LETTER	10 FEET FROM THE North	2310 LINE AND FEET FROM	Borreturne daaen
-		38E	
THE West LINE, SECTION	30 TOWNSHIP		
	15. Elevation (Show whether	DE BT CP ata L	12. County
	3135' I		Lea
$1_{6}$			
		Nature of Notice, Report or Otl	
NOTICE OF IN	TENTION TO:	SUBSEQUENT	REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	& test additional sones,
OTHER	[~]	OTHER CALVANCES SECURI	
			· · · · · · · · · · · · · · · · · · ·
17. Describe Proposed or Completed Ope work) SEE RULE 1103.	erations (Clearly state all pertinent det	tails, and give pertinent dates, including	estimated date of starting any proposed
1. Moved in workover rig	and nulled rods and tw	hine	
2. Ran drill pipe and bi			
3. Drilled out cement an			
4. Circulated hole clean		bit	
5. Perforated 5-1/2"OD c			
	- 3651' - 5' - 5 shots		
3661	- 3670' - 9' - 9 shote	I	
3708	- 3710' - 2' - 2 shots	l	
	- 3724' - 4' - 4 shets		
	- 3767' - 5' - 5 shots		
	3782' - 7' - 7 shots		
<u>3791</u>	- 3793' - 2' - 2 shots		
	- 34 shets		
6. Ran tubing with "RTTS			
3737-51'. Set packer	at 3757', pumped in 7 h	bls. acid, communicated.	Set packer at 3732'.
7. Treated down tubing i	nto perforations 3762-9	3' with 1000 gallons "H	A" Acid and 20 ball
		ing, packer and bridge p	
packer at 3705', test	ed and had communicatio	ms 3702-68'. Set packer	at 3675".
18. I hereby certify that the information a	above is true and complete to the best	of my knowledge and belief.	
) OLIGINAL ) w w	il stabon		
SIGNED V. E. F	TAPOTIAT. TILLE DI	trict Production Manager	DATE October 1, 1968
North.			OCT 4 1968
APPROVED BY	Aney TITLE_		DATE
CONDITIONS OF APPROVAL. IF ANY:			
	/		

- 8. Treated down tubing into perforations 3708'-24' with 1000 gallons "BDA" Acid and 20 ball sealers. Lowered tubing and packer, raised and reset bridge plug at 3675', set packer at 3615'.
- 9. Treated down tubing into perforations 3646-70' with 1000 gallons "BDA" Acid and 30 ball sealers. Pulled tubing, packer and plug.
- 10. Ran 161 Jts. (3679' LTM) 2-3/8"GD R 1 J-55 tubing and set at 3679', seating nipple 3656' perforations 3657-60'. Ran roda with pump pet at 3656'.
- 11. Ran rods with pump set at 3656'.
- 12. Well returned to producing status September 30, 1968, pumped 2 bbls oil 6 31 bbls water in 24 hours.