

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>

5. State Oil & Gas Lease No.

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER - <b>Water Injection Well</b>		7. Unit Agreement Name <b>West Dollarhide Queen Sand Unit</b>
2. Name of Operator <b>Skelly Oil Company</b>		8. Farm or Lease Name <b>West Dollarhide Queen Sand Unit</b>
3. Address of Operator <b>P. O. Box 1351, Midland, Texas 79701</b>		9. Well No. <b>5</b>
4. Location of Well UNIT LETTER <b>C</b> <b>2310</b> FEET FROM THE <b>West</b> LINE AND <b>990</b> FEET FROM THE <b>North</b> LINE, SECTION <b>30</b> TOWNSHIP <b>24S</b> RANGE <b>38E</b> NMPM.		10. Field and Pool, or Wildcat <b>Dollarhide Queen</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3158' KB</b>		12. County <b>Lea</b>

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) Moved in pulling unit 3-31-73. Pulled tubing and safety joint. Unable to pull packer. Left packer in the hole at 3529'.
- 2) Set 5-1/2" cast iron bridge plug at 3514'. Loaded hole with 10.2# mud.
- 3) Spotted 15 sack cement plug at 3318-3514', 100 sack cement plug 926-1808', and 10 sack cement plug from surface to 20'.
- 4) Installed dry hole marker.

8-5/8" OD 24# casing set at 1235' and 5-1/2" OD 15.5# casing set at 3784' were left in the hole. All intervals not cemented were filled with 10.2# mud.

Well plugged and abandoned 4-1-73.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED D. R. Crow TITLE Lead Clerk DATE April 10, 1973

APPROVED BY John W. Runyan TITLE Geologist DATE April 11, 1973

CONDITIONS OF APPROVAL, IF ANY: