

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
CITY SECTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

3a. Indicate Type of Lease	
State ☐	Fee ☒
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator

Texaco Producing Inc.

Address of Operator

P.O. Box 728, Hobbs, NM 88240

Location of Well

UNIT LETTER C 535 FEET FROM THE North LINE AND 2310 FEET FROM
THE West LINE, SECTION 30 TOWNSHIP 24S RANGE 38E N.M.P.M.

7. Unit Agreement Name

West Dollarhide Drinkard

8. Farm or Lease Name Unit

9. Well No.

17

10. Field and Pool, or Wildcat

Dollarhide Tubb Drinkard

11. Elevation (Show whether DF, RT, GR, etc.)

3156' DF

12. County

Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

1. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) MIRU. Pull rods and pump.
- 2) Install BOP. TOH w/production tubing.
- 3) TIH w/4 3/4" bit and casing scraper to PBTD and circulate well clean.
- 4) Spot 2 drums convertor mixed in 2 bbls fresh water across perforations (6614'-6710'). TOH.
- 5) Perforate Dollarhide Tubb Drinkard w/2 SPF at 6734'-40', 48-50, 78-86, 6815-20, 35-38, 43-47, 68 shots.
- 6) TIH w/pkr to 6520'. Test workstring to 5000 psi. Swab convertor back.
- 7) Acidize Dollarhide Tubb Drinakrd perforations w/10,000 gals 15% NEFE HCL w/ball sealers 4-5 BPMAIR (Total 212 perfs).
- 8) Swab acid back and squeeze 2 drums scale inhibitor mixed in 30 bbl fresh water and flush w/100 bbl fresh water mixed in 5 gal. surfactant.
- 9) TOH w/pkr and workstring.
- 10) TIH w/prod. tbg, anchor, rods and pump. Place well on production.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. W. Browning

TITLE District Admin. Supervisor

DATE 01/23/87

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____

TITLE _____

DATE JAN 30 1987

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
JAN 29 1971
OCC
HOBBS OFFICE