

NEW MEXICO OIL CONSERVATION COMMISSION

3-MOCC-HOBBS
1-R. J. STARRAK-TULSA
1-A. B. CARY-MIDLAND
1-ELB, ENGR.
1-CK, FOREMAN
1-BB, OFC TECH
1-FILE

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSED TO ABANDON OR TO PERFORM PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT TO ABANDON CHECK FOR SUCH PURPOSES.)

OIL WELL ☐ GAS WELL ☐ OTHER- INJECTION WELL

Name of Operator
Getty Oil Company

Address of Operator
P. O. Box 730, Hobbs, NM 88240

Location of Well

UNIT LETTER N 330 FEET FROM THE South LINE AND 2310 FEET FROM
The West LINE, SECTION 3C TOWNSHIP 24S RANGE 38E NMPH.

15. Elevation (Show whether DF, RT, CR, etc.)

3120' DF

5a. Indicate Type of Lease

State ☐ Fee ☒

5. State Oil & Gas Lease No.

7. Unit Agreement Name

6. Form or Lease Name

West Dollarhide Drk. Uni

9. Well No.

31

10. Field and Pool, or Valued

Dollarhide Tubb-Drinkard

12. County

Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
EMERGENTLY ABANDON ☐
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

OTHER Plugback ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig up pulling unit and install BOP.
2. POH with tbg. and pkr.
3. Set EZ drill BP over Abo zone.
4. Run packer and tbg. back.
5. Set packer within 100' of perforations.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Neil Crockett
Date B. Crockett

TITLE Area Superintendent

DATE 1-16-80

APPROVED BY
Orig. Signed by
Jerry Sexton

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY

JAN 16 1980