

DISTRIBUTION		
AREA		
FILE		
LOGS		
AND OFFICE		
REVISION		

NEW MEXICO OIL CONSERVATION COMMISSION

3-NEOCC-HOBBS
 1-R. J. STARRAK-TULSA
 1-A. B. CARY-MIDLAND
 1-ELB, ENGR.

1-CK, FOREMAN
 1-BB, OFC TECH
 1-FILE

Superseries 006
 C-102 and C-103
 Effective 1-1-65

50. Indicate Type of Lease
 State ☐ Fee ☒

51. State Oil & Gas Lease No.

52. Unit Agreement Name

53. Form of Lease Name
 West Dollarhide Drk. Uni

54. Well No.
 30

55. Field and Pool, or Wildcat
 Dollarhide Tubb Drinkard

56. County
 Lea

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR NOTICES TO ABANDON OR TO RE-ENTER A WELL OR TO A DIFFERENT RESERVOIR.
 USE APPLICATION FOR ABANDONMENT OR RE-ENTRY FOR SUCH PURPOSES.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator
 Getty Oil Company

Address of Operator
 P. O. Box 730, Hobbs, NM 88240

Location of Well
 UNIT LETTER K 1980 FEET FROM THE South LINE AND 2310 FEET FROM
 THE West LINE, SECTION 30 TOWNSHIP 24S RANGE 38E NMPH.

15. Elevation (Show whether DF, RT, GR, etc.)
 3121' DF

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
 NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☒ Plugback	CASING TEST AND CEMENT JOBS ☐	

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 100.

1. Rig up pulling unit.
2. Pull rods and pump.
3. Install BOP and pull tbq.
4. Set EZ drill BP over Abo zone.
5. Run tbq. pump, and rods.
6. Return well to production.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

DATE 1-16-80 TITLE Area Superintendent DATE 1-16-80

DATE 1-16-80 SIGNED BY Jerry Sexton TITLE Dist 1, Supv. DATE JAN 30 1980

CONDITIONS OF APPROVAL, IF ANY