

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-101
Revised 10-1-79

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

3-NMOCD-Hobbs 1-Foreman-CK
1-File 1-Laura Richardson-Midland
1-Engr. Jim

5a. Indicate Type of Lease	
State ☒	For ☐
5. State Oil & Gas Lease No.	
B-9311	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER		7. Unit Agreement Name
2. Name of Operator Getty Oil Company		8. Farm or Lease Name West Dollarhide Queen Sand Unit
3. Address of Operator P.O. Box 730, Hobbs, NM 88240		9. Well No. 20
4. Location of Well UNIT LETTER <u>N</u> <u>467</u> FEET FROM THE <u>South</u> LINE AND <u>2310</u> FEET FROM THE <u>West</u> LINE, SECTION <u>30</u> TOWNSHIP <u>24S</u> RANGE <u>38E</u> NMPM.		10. Field and Pool, or Wildcat Dollarhide Queen
11. Elevation (Show whether DF, RT, GR, etc.) 3109'		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☒	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	
		OTHER ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6/16/82 Rig up. Pull rods and tubing (2 3/8").
6/17/82 Ran 6 1/4 x 3 3/4, shoe w/ 4 jts of WP to 3615'. Clean fill to 3620'. Cut on metal @ 3620.5, pull mill. Ran 6 1/4 x 5' cut rite shoe. Mill from 3520 1/2 - 22' metal & scale
6/18/82 Lower mill tag 3622-26. 4 hrs. Pulled mill. Reran 5 1/4 x 5" 5' shoe & 3 jts of 6" OD x 5 3/8" WP, 3540'.
6/19/82 Mill from 3622-26 1/2.
6/21/82 Ran 6 1/2 x 4 7/8" shoe on 3 jts of 5 3/4" x 5" WP. Mill 3626'-33' on metal, wash to 3685'.
6/22/82 Recovered 7' csg. Ran 6 1/8" bit and wash 3645-3697'.
6/23/82 Ran 6 1/8" bit and tag @ 3625'. Drill to 3703'.
6/24/82 Ran tension pkr on 2 3/8" tbg and set @ 3455'. Perfs @ 3565'-3615' and O.H. @ 3650'-3710'. By Dowell treat w/ 8000 gals 15% NE HCL and 2000# salt in 4 stages. Max press. 1670#, Min press. 1200#, ISIP 1000#, 15 min 940#, Rate 4 BPM.
6/25/82 Ran 120 jts of 2 3/8" tbg and SN set tbg @ 3611' w/ SN @ 3576'. Ran 2" x 1 1/2" x 16' pump and rig down. Placed well back on production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED D. R. Crockett TITLE Area Superintendent DATE June 29, 1982

APPROVED BY SA ORIGINAL SIGNED BY SA DATE JUL 8 1982
CONDITIONS OF APPROVAL, IF ANY: