

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions on re-
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL ☒ WELL GAS ☐ WELL OTHER ☐		6. LEASE DESIGNATION AND SERIAL NO. NM 10186
2. NAME OF OPERATOR TEXACO INC		7. UNIT AGREEMENT NAME WEST DOLLARHIDE DRINKARD UNIT
3. ADDRESS OF OPERATOR P.O. BOX 728, HOBBS, N.M. 88240		8. FARM OR LEASE NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface UNIT LETTER A, 990' FNL & 330' FEL		9. WELL NO. 46
14. PERMIT NO.		10. FIELD AND POOL, OR WILDCAT DOLLARHIDE TUBB DRINKARD
15. ELEVATIONS (Show whether DF, ET, OR, etc.) 3148 D.F.		11. SEC., T., R., N., OR S.E., AND SUBDIVISION OR AREA SEC 31, T24S, R38E
		12. COUNTY OR PARISH LEA
		13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANE

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) CHECK CEMENT TOP AS REQUESTED
(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

- 1) ON MAY 18, 1988 MIRU. POHW/PRODUCTION EQUIPMENT. TIH w/6" BIT. TAG TOP OF LINER AT 4884' POOH.
 - 2) TIH w/5" R.B.P. SET R.B.P. AT 4910' POOH. RAN CEMENT BOND LOG. TOC AT 3280'.
 - 3) TIH AND RETRIEVED R.B.P. TOOH. TIH w/4 1/4" BIT. C/O WELL TO 6485' TOOH.
 - 4) TIH w/5" PKR. SET PKR AT 6282'. ACIDIZE DOLLARHIDE TUBB DRINKARD PERFORATIONS (6418'-6499') w/5000 GALS 15% NEFE ACID & 500 LB. R. S. IN GELLED BR.
 - 5) SWABBED 2 HRS, RECOVERED 55 BLW. PUMP 110 GALS SCALE INHIBITOR w/30 BBS FRESH WATER. FLUSHED w/200 BBS PROD. WATER. S.I. OVERNIGHT.
 - 6) TOOH. TIH w/PRODUCTION EQUIPMENT. RIG-DOWN
- 24 HR POTENTIAL TEST, ENDING JUNE 23, 1988 Pmp 19°/96°/247, GRAVITY 37.5 @ 60°.

18. I hereby certify that the foregoing is true and correct

SIGNATURE

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY

TITLE

DATE

ACCEPTED FOR RECORD

DATE

*See Instructions on Reverse Side