

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN ORIGINAL
(Other instructions
verse side)

Expires August 31, 1983

5. LEASE DESIGNATION AND SERIAL NO.

LE-064052

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

NM-10186

7. UNIT AGREEMENT NAME

WEST DOLLARHIDE
DRINKARD UNIT

8. FARM OR LEASE NAME

9. WELL NO.

50

10. FIELD AND POOL, OR WILDCAT

DOLLARHIDE TUBB DRINKARD

11. SEC., T., R., M., OR BLK. AND
SUBVY OR AREA

SECT 31, T-24S, R-38E

12. COUNTY OR PARISH

LEA

13. STATE

NEW MEXICO

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL ☒ GAS ☐ OTHER ☐
WELL WELL

2. NAME OF OPERATOR

TEXACO PRODUCING INC

3. ADDRESS OF OPERATOR

P.O. BOX 728, HOBBS, NEW MEXICO 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

UNIT LETTER G, 2130' FNL & 1650' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3135' D.F.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)

- 1) MIRV. PULL RODS AND PUMP. TOH W/ PRODUCTION TBG.
- 2) GIH W/ 4 1/4" BIT. DRILL CMT, LANDING COLLAR, AND C/O TO 6600'. TOH
- 3) PERFORATE DOLLARHIDE TUBB DRINKARD POOL W/ 2SPF AT 6385'-87', 90'-49', 6409'-11',
49'-50', 73'-77', 6498'-6513', 6518'-24' (92 SHOTS)
- 4) TIH W/ PKR TO 6300'. TEST WORKSTRING TO 5000 PSI. ACIDIZE DOLLARHIDE TUBB DRINKARD
PERFORATIONS (6385'-6524') W/ 7500 GALLONS 15% NEFE HCL W/ BALL SEALERS @ 4 BPN
- 5) SWAB ACID BACK. SQUEEZE 2 DRUMS SCALE INHIBITOR MIXED IN 30 BBLS FRESH
WATER AND FLUSH W/ 250 BBLS FRESH WATER MIXED WITH 50 GALLONS SURFACTANT.
- 6) TOH W/ PKR AND WORKSTRING. S.I. - 24 HRS
- 7) T.I.H. W/ PROD. EQUIPMENT
- 8) TEST AND SUBMIT TO NMCCD FOR ALLOWABLE.

18. I hereby certify that the foregoing is true and correct

MAY 3 1988

SIGNED

KL Johnson

TITLE AREA SUPERINTENDENT

DATE

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

5-13 88

*See Instructions on Reverse Side