	- I N	EW MEXICO OIL CO	ONSERVATI	ON COmmission		FORM C-110
TA FF   E   G.S.   NO OFFICE	CERTIFIC	SANTA   CATE OF COMP ) TRANSPORT (	FE, NEW ME	AND AUTHORIZ	ATION	(Rev. 7-60)
ANSPORTER GAS		رية في بالم				<u> </u>
ERATOR	FILE THE OF	RIGINAL AND 4 COPI		Lease Wast Dol	larhide	Well No.
ompany or Operator Skelly Cil	L Company			Grown Sand Un		33
Init Letter Section	Township	Range	j~E	County		
•••• 31				Kind of Lease (State, F		Federal
If well produces oil or c		Thide Queen	Section	Township	Range	38-E
give location of t	tanks	нДн	<b>31</b>	24- dress to which approved		rm is to be sent)
thorized transporter of oil	or condensate 🗌			20x 1520, Midle		
ICHES REA M		ctually Connected?	Yes			
uthorized transporter of casing he		T		dress to which approved	copy of this fo	rm is to be sent)
RI Peso Matu	ural Gas Compet	<b>?</b>	Ĭ	) Paso, Texas		
gas is not being sold, give reaso						
	1		Change in Own	roper box) ership below)	•• 📑	
Change i Oil .	l in Transporter (check on Dry ng head gas . Con	Gas	Change in Own	ership	4	
Change i Oil . Casir Remarks Dodicatod t This woll w	in Transporter (check on Dry ng head gas Con to Nest Dollarn	ie) ( Gas [] idensate []	Change in Own Other (explain Charge 34 Unit off	ership	1, 1963	Elliett
Change i Oil . Casir Remarks DodLuatod t This woll w Well No. 2.	in Transporter (check on Dry ng head gas . D Con to West Dollarn and formerly kn	ie) Gas [] Idensate [] Ide Queen Sand	Change in Own Other (explain Charge 34 Unit off Unit off	ership below) mus of Laass ording January ty Company's -	1, 1963 Federal 1	Elliott
Change i Oil . Casir Remarks Dodloatod t This woll w Well No. 2. The undersigned certifies that	in Transporter (check on Dry ng head gas . D Dry to West Dollart to West Dollart to Nest Dollart to Hest Dollart to Hest Dollart	ide Queen Send	Change in Own Dither (explain Charge 3 Urill off Urill off and Royalt ervation Com	ership below) mus of Laass ording January ty Company's -	1, 1963 Federal 1	Elliett
Change i Oil . Casir Remarks DodLostod t This woll & Well No. 2. The undersigned certifies that Exec	in Transporter (check on Dry ng head gas . D Dry ng head gas . Con to West Dollart to West Dollar	idensate	Change in Own Other (explain Charge 34 Unit off Unit off	ership	1, 1963 Federal I	Elliott
Change i Oil . Casir Remarks DodLostod t This woll & Well No. 2. The undersigned certifies that Exec	in Transporter (check on Dry ng head gas . D Dry to West Dollart to West Dollart to Nest Dollart to Hest Dollart to Hest Dollart	idensate	Change in Own Other (explain Charge in Charge in Unit off Unit off ine Royal ervation Com	ership below) mus of Laass ording January ty Company's -	1, 1963 Federal I	Elliott
Change i Oil . Casir Remarks DodLostod t This woll & Well No. 2. The undersigned certifies that Exec	in Transporter (check on Dry ng head gas . D Dry ng head gas . Con to West Dollart to West Dollar	ations of the Oil Cons	Change in Own Other (explain Charge in Charge in Unit off Unit off ine Royal ervation Com	ership	1, 1963 Federal D mplied with. Asb	Elliott
Change i Oil . Casir Remarks Dodicated t This woll & Well No. 2. The undersigned certifies that Exec OIL CONSER	in Transporter (check on Dry ng head gas . D Dry ng head gas . Con to West Dollart to West Dollar	ide Queen Send	Change in Own Other (explain Charge in Unit off Unit off ne Royal ervation Com	ership	1, 1963 Federal D mplied with. Asb	Elliott