

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30 025 12293
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	WEST DOLLARHIDE DRINKARD UNIT
8. Well No.	66
9. Pool Name or Wildcat	DOLLARHIDE TUBB DRINKARD
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

SUNDRY NOTICES AND REPORTS ON WELL (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	PO BOX 3109, MIDLAND, TEXAS 79701
4. Well Location	Unit Letter <u>K</u> : <u>2312</u> Feet From The <u>SOUTH</u> Line and <u>2309</u> Feet From The <u>WEST</u> Line Section <u>31</u> Township <u>24S</u> Range <u>38E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILL OPERATIONS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: Request temporarily abandon status <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Texaco E & P Respectfully request permission to temporarily abandon this well.  
Reason: Engineering staff is currently evaluating this wellbore for horizontal re-entry.  
Approx. Start date: 6/11/01

6/11/01 MIRU Key Well Service(Louis Anaya). Bled off well and unseated pump. Poh and lay down 67 7/8" rods and 187 3/4" rods and pump. Bled off backside and NU bop and got ready to pull pipe. SION  
6/12/01 Bled well down and poh w/204 jts 2 3/8" tbg, perf sub and mud jt. Tih w/bit and scraper to 6325' and toh. By Rotary Wireline set CIBP at 6173'. Load csg and chart test w/550 psi and held good. Dumped 35' of cmt on CIBP making PBTD 6138'. SION.  
6/13/01 Tih w/195 jts 2 3/8" tbg and displace csg w/prk fluid. Toh and lay down tbg. ND bop and flange up wellhead. By A&B Transport chart test csg w/540 psi for 30 minutes and held good. Rig down  
Send C-103 subsequent report and chart to NMOCD.

This Approval of Temporary  
Abandonment Expires 7-2-06

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE M. Quintana TITLE Engineering Assistant DATE 6/2/01  
TYPE OR PRINT NAME Mike Quintana Telephone No. 505-394-9307

(This space for State Use)

APPROVED BY [Signature] TITLE [Signature] DATE 6/2/01  
CONDITIONS OF APPROVAL, IF ANY: