

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-025-12306
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-9311
7. Lease Name or Unit Agreement Name West Dollarhide Queen Sand Unit
8. Well No. 38
9. Pool name or Wildcat Dollarhide Queen
10. Elevation (Show whether DF, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER Water Injection
2. Name of Operator Sirgo Operating, Inc.
3. Address of Operator P.O. Box 3531, Midland, Texas 79702
4. Well Location Unit Letter <u>K</u> : <u>2310</u> Feet From The <u>South</u> Line and <u>1650</u> Feet From The <u>West</u> Line Section <u>32</u> Township <u>24S</u> Range <u>38E</u> NMPM Lea County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
1-20-90 RIH w/CR to 3550'. Squeeze 30 sx Class C. Spot 5 sx. on top. Circ w/ 10.2 brine gel to 2590'. POH & perf @ 2590'. RIH & set CR @ 2490'. Squeeze w/30 sx Class C. PU & spot 5 sx on top. Circ 10.2 brine gel to 1290'. POH & perf @ 1290'. RIH w/CR to 1130' & squeeze w/45 sx. Class C. PU & spot 5 sx on top. Circ 10.2 brine gel to 50'. Cmt w/10 sx Class C from 50' to surface. Cut off wellhead & install P&A marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.
SIGNATURE Bonnie Otavater TITLE Production Technician DATE 1-31-90
TYPE OR PRINT NAME _____ TELEPHONE NO. _____

(This space for State Use)
APPROVED BY Jack Griffin OIL & GAS INSPECTOR DATE APR 26 1990
CONDITIONS OF APPROVAL, IF ANY: _____

8