

OIL CONSERVATION DIVISION

P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-73

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B-9311	

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input type="checkbox"/> GAS <input type="checkbox"/> OTHER- Water injection well		7. Unit Agreement Name West Dollarhide Queen Sand Unit
2. Name of Operator Sirgo-Collier, Inc.		8. Farm or Lease Name
3. Address of Operator P. O. Box 3531, Midland, Texas 79702		9. Well No. 38
4. Location of well UNIT LETTER K, 2310 FEET FROM THE South LINE AND 1650 FEET FROM THE West LINE, SECTION 32 TOWNSHIP 24S RANGE 38E NMPM.		10. Field and Pool, or Wildcat Dollarhide Queen
15. Elevation (Show whether DF, RT, GR, etc.) 3155' GR		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Sirgo-Collier, Inc. proposes to plug and abandon the West Dollarhide Queen Sand Unit Well No. 38 as follows:

Move in and rig up pulling unit. Pull tubing and packer.  
TIH with 5-1/2" cement retainer and set at 3547'. Squeeze with 35 sx Class "C".  
Spot 5 sx Class "C" from 3512' to 3547'.  
Pull up to 3505' and circulated hole with 10.2# brine.  
TIH and perf 5-1/2" casing at 2615' with 4 SPF.  
TIH with cement retainer and set at 2465'. Squeeze with 45 sx Class "C".  
Spot 5 sx Class "C" from 2465' to 2430'.  
TIH and perf 5-1/2" casing at 1290' with 4 SPF.  
TIH with cement retainer and set at 1152'. Squeeze with 45 sx Class "C".  
Spot 5 sx Class "C" from 1152' to 1117'.  
Spot 10 sx from 50' to surface.  
Cut off wellhead, weld on steel plate and dry hole marker. Fill cellar, cut off dead men and level location.

THE COMMISSION MUST BE NOTIFIED 24  
HOURS PRIOR TO THE BEGINNING OF  
PLUGGING OPERATIONS FOR THE C-103  
TO BE APPROVED

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Amy L. Whitley TITLE Agent DATE March 22, 1988

ORIGINAL SIGNED BY JERRY SEXTON  
APPROVED BY DISTRICT 1 SUPERVISOR TITLE \_\_\_\_\_ DATE MAR 25 1988

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED  
MAR 24 1988  
OCCD  
HOBBS OFFICE