

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-12313
5. Indicate Type of Lease STATE <u>XX</u> FEE <u> </u>
6. State Oil & Gas Lease No. B-9311
7. Lease Name or Unit Agreement Name West Dollarhide Drinkard Unit
8. Well No. 70
9. Pool name or Wildcat Dollarhide Tubbs Drinkard

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Texaco Exploration & Production, Inc.	
3. Address of Operator P. O. Box 3109, Midland, TX 79702	
4. Well Location Unit Letter <u>0</u> : <u>2130</u> Feet From The <u>East</u> Line and <u>510</u> Feet From The <u>South</u> Line Section <u>32</u> Township <u>24S</u> Range <u>38E</u> NMPM <u>Lea</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3166 DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1) Notify Oil Conservation of intent to plug

2) M.I.R.U., NU BOPE, P.O.H. W/Tbg

3) Set CIBB @ 5550 W/20 sx cement

4) CIRC 9.5# mud to surface

5) Pull to 3625 & spot 20 sx to 3525 (Queen)

6) Pull up to 3200 & spot 20 sx shoe plug top Est @ 3100' (Tag)

7) Pull up to 2545 & spot 20 sx to 2445' (Bottom Salt)

8) Pull up to 1302 & spot 20 sx to 1202' (Top Salt)

9) P.O.H. set surface plug from 50-0 10 sx

10) R.D.M.O. cut off well head & set dry hole marker, clean location

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Dave Deax TITLE Reservoir Engineer DATE
TYPE OR PRINT NAME Dave Deax TELEPHONE NO. 915-688-4492

(This space for State Use)

APPROVED BY TITLE DATE

CONDITIONS OF APPROVAL, IF ANY:

DEC 11 1997