

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-101
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

0+5-NMOCD-Hobbs 1-JA 1-WIO ARCO 1-WIO Gulf
1-File 1-BB 1-WIO Amoco
1-Engr Jim 1-BW, 1-CB, 1-CP
1-Foreman CK 1-Laura Richardson-Midland

5a. Indicate Type of Lease State ☒ For ☐
5. State Oil & Gas Lease No. B-9613

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.

1. OIL ☐ GAS ☐ OTHER- Water Injection Well	7. Unit Agreement Name West Dollarhide Drinkard
2. Name of Operator Getty Oil Company	8. Farm or Lease Name Unit
3. Address of Operator P.O. Box 730, Hobbs, NM 88240	9. Well No. 53
4. Location of Well UNIT LETTER F 2310 FEET FROM THE North LINE AND 1980 FEET FROM West 32 TOWNSHIP 24S RANGE 38E NMPM.	10. Field and Pool, or Wildcat Dollarhide Tubb-Drinkard
15. Elevation (Show whether DF, RT, GR, etc.) 3181' DF	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☒
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4/2/83 Plug and abandon. Moved in and rigged up unit. N.D. tree and N.U. BOP.
4/4/83 Welex ran cmt bond log 3923 to surf. Pick up 2 3/8" workstring. Ran to 4003'. Set down. Pull tbq.
4/5/83 Ran 5 1/2" Howco retainer set @ 3910'. Howco squeeze w/ 500 sxs class "C" left 10' in retainer. Had communication. Reverse out 500 sxs. Pull tbq and stinger. Ran RTTS pkr. Hole in csg @ 3742'. Test pipe @ 3616 OK, 1000#. Pull pkr.
4/6/83 Howco ran 5 1/2" EZ drill retainer. Set @ 3585'. Howco squeezed w/ 500 sxs "C", 2% CCL. Reverse out 3 1/2 sxs. Pull tbq and stinger. Welex ran temp base log 1300-3563'. Cmt top 3510'. Perf 2 holes @ 3052'. Pump up to 1500#, no break. Perf 2 holes @ 325.
4/7/83 Ran tbq. Howco spot 40 sacks class "C" neat 2692-3197'. Pull tbq. Pump 233 sxs "C". Circulate out 8 5/8". Left 5 1/2" csg full.
4/8/83 Install dry hole marker. Rig down. P&A.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signed [Signature] TITLE Area Superintendent DATE April 14, 1983
APPROVED BY [Signature] TITLE OIL & GAS INSPECTOR DATE MAY 5 1983
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
APR 15 1983
C.C.D.
HOBBS OFFICE