

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

| | |
|------------------------|--|
| NO. OF COPIES RECEIVED | |
| DISTRIBUTION | |
| SANTA FE | |
| FILE | |
| U.S.G.S. | |
| LAND OFFICE | |
| OPERATOR | |

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

3-NMOCD-P.O. Box 1980 1-File

Hobbs, NM 88240

1-JIM, Engr.

1-KINGSTON, Foreman

Form C-101
Revised 10-1-78

| | |
|---|------------------------------|
| 5a. Indicate Type of Lease | |
| State <input checked="" type="checkbox"/> | Fee <input type="checkbox"/> |
| 5. State Oil & Gas Lease No. | |
| B-9613 | |

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

| | |
|--|---|
| 1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/> Water Injection Well | 7. Unit Agreement Name Unit West Dollarhide Drinkard |
| 2. Name of Operator Getty Oil Company | 8. Farm or Lease Name Unit West Dollarhide Drinkard |
| 3. Address of Operator P.O. Box 730 | 9. Well No. 53 |
| 4. Location of Well UNIT LETTER F, 2310 FEET FROM THE North LINE AND 1980 FEET FROM THE West LINE, SECTION 32 TOWNSHIP 24S RANGE 38E NMPM. | 10. Field and Pool, or Wildcat Dollarhide Tubb-Drinkard |
| 15. Elevation (Show whether DF, RT, GR, etc.) 3181' DF | 12. County Lea |

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

| | | | |
|--|---|--|---|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> | REMEDIAL WORK <input checked="" type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> | PLUG AND ABANDONMENT <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | OTHER <input type="checkbox"/> | CASING TEST AND CEMENT JOBS <input type="checkbox"/> | |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4/8/82 Tubing parted.
4/9/82 Ran overshot to 4151'. No recovery
4/10/82 Ran 4 3/4 x 3 1/2" shoe 3 jts wash pipe wash 4151-4309. Pull wash pipe. Top fish @ 4220'. Pkr @ 5871'.
4/12/82 Ran overshot & caught fish @ 4220'. Recovered 1 jt. Re-ran O.S. & caught fish @ 4251'. Recovered 2 jts tbgs.
4/13/82 Ran 4 3/4 x 3 1/2 shoe. 118' of 4 1/2" wash pipe. Washed 4314-4432' for 2 hrs. Pulled wash pipe. Recovered 5" 2 3/8" tubing. Ran overshot. Fish @ 4314'. Recovered 6 jts. 188'.
4/14/82 Ran 4 3/4" x 3 1/2" shoe, T-dog and 118' W.P. Wash 4498'-4623'. Pull W.P. & recovered all fish. 59 jts and AD packer. Ran 4 3/4" bit to 4486'.
4/15/82 Finish TIH w/4 3/4" bit & 2 7/8" tbgs. Reversed clean 5 1/2" csg. From 4623' to top of 4" liner @ 5752'.
4/16/82 TIH w/5 1/2" Baker pkr. Press to 1000#, held @ 3752', leaked @ 3780'. TO run 3 1/4" bit, 2 3/8" and 2 7/8" tbgs to 5859'.
4/17/82 C.O. Scale, rubber and fill from 6104' to 6700'.

(Cont'd on back)

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Dale R. Crockett TITLE Area Superintendent DATE May 6, 1982

APPROVED BY JERRY SEXTON TITLE DATE MAY 10 1982
CONDITIONS OF APPROVAL: DISTRICT 1 SUPER

4/19/82 Ran bridge plug & pkr. Tight spot at 4221'. Pull pkr, left plug. Ran retrieving tool but didn't recover plug. Ran lead block and it showed jagged csg.

4/20/82 SD wind.

4/21/82 Ran 4 3/4" shoe & tagged 4221-231' pulled mill. Ran retrieve tool, did not catch. Ran imp block (csg looked parted).

4/22/82 Ran con cave mill 4 3/4" mill 4219-4220'.

4/23/82 Ran mill 4220-4222'. Pulled concave mill. Ran block showed 2 marks.

4/24/82 Ran concave mill. Mill 4222'-24'. Pull mill & ran impression block, showed nothing.

4/26/82 TIH w/4 3/4" shoe. Drilled 4324-25' (1') TOH rec 2 small pieces of csg. TIH w/4 3/4 x 3 1/2" shoe. Ran shoe, jars, DC's and 2 7/8" tbg. Milled 4225-4226'.

4/27/82 Pulled shoe. Ran new shoe and tagged @ 4135'. Made no hole. Pulled mill. Ran impression block (4 1/2") to 3987'. Slab of casing looking up. Ran 4 3/4" shoe and milled 3987-4003'.

4/29/82 Lay down 2 3/8" Inj. Tubing. Rigged down and moved out.

RECEIVED

MAY 7 1982

HOLLYWOOD