

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-79

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

0+6-NMOCD-Hobbs 1-Mr. J.A.-Midland
1-File 1-Laura Richardson-Midland
1-Engr. Jim 1-JA
1-Foreman CK 1-BB

1. Indicate Type of Lease	State ☒ Fee ☐
2. State Oil & Gas Lease No.	B-1732

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REOPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT TO DRILL (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☐ OTHER- Injection Well	7. Unit Agreement Name West Dollarhide Drkd. Un.
2. Name of Operator Getty Oil Company	8. Farm or Lease Name
3. Address of Operator P.O. Box 730, Hobbs, NM 88240	9. Well No. 57
4. Location of Well UNIT LETTER F 629 FEET FROM THE East LINE AND 1980 FEET FROM THE North LINE, SECTION 33 TOWNSHIP 24S RANGE 38E N.M.P.M.	10. Field and Pool, or Wildcat Dollarhide Tubbs Drkd.
15. Elevation (Show whether DF, RT, GR, etc.) 3197' KB	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	OTHER ☒ Plugged back

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3/2/84 Release pkr, pulled 1 jt.
3/3/84 Pkr stuck @ 6396' lowered pkr to 6490'. Backed-off safty jt. Pulled tbq 209 jts. Ran 3 3/4" swage. Swage 6398-6400'.
3/5/84 Ran 4 1/4" swage from 6398-98 1/2. Pulled swage & ran 3 15/16" swage. Swage from 6398-6400'.
3/6/84 Ran 4 1/4" swage. Swaged 1 hour @ 6398' w/ no progress. Ran new 4 1/4" swage.
3/7/84 Swaged w/ 4 1/2" swage for 1/2 hour. Ran 4 1/4" tapered mill. Tagged @ 6399'. Milled 3'. Washed to 6414'.
3/8/84 Pulled 4 1/4" tapered mill. Ran top half of 5 ft jt & attempted to screw in pkr @ 6490'. Unable to pull tools. Ran 3 7/8" over shot to 6490'.
3/9/84 Pulled over shot no recovery. Ran spear 6528', circ. 3' & stop. Pulled spear. No recovery. Ran 4 1/4 x 2 1/2" shoe to 6415'. Drilled 3' scale. Ran 6531' mill 1' on packer.
3/10/84 Ran mill from 6532 to 6533'. Pulled mill. Ran 3 3/4" overshot 6532' wash 10. Pulled tool.
3/12/84 Ran 3 3/4" overshot to 6532' & pulled off. Pulled tools and ran new grapple, caught fish @ 6532'. Recovered packer & all fish.
3/13/84 Ran 4 1/4" bit & cleaned out 6545-6744'.
3/14/84 Ran Howco CI plug and set @ 6700'.
3/15/84 Ran 5" x 2 3/8" AD-1 pkr on 202 jts ipc tbq 6248'. Displace treated brine. Cont.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Dale R. Crockett TITLE Area Superintendent DATE March 22, 1984

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR

CONDITIONS OF APPROVAL, IF ANY:

MAR 26 1984

3/15/84 Cont'd Set pkr & test to 800#-OK.

6

RECEIVED
MAR 26 1984