

Submit 3 Copies To Appropriate District
Office
District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Avenue, Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

WELL API NO.
30-025-12345

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name:

West Dollarhide Drinkard Unit

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well:

Oil Well ☐ Gas Well ☐ Other Injection

2. Name of Operator
Chevron USA, Inc.

8. Well No.
58 WIW

3. Address of Operator
15 Smith Rd. Midland, Tx 79705

9. Pool name or Wildcat
Dollarhide, Drinkard

4. Well Location

Unit Letter K : 1980 feet from the south line and 630 feet from the east line

Section 33 Township 24-S Range 38-E NMPM County Lea

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. Tag top of fish @ 6383(ok w/OCD) spot 65sx plug fr/6383 to 5940(Drinkard 7" shoe top of liner) Tag @ 5928
2. Displace hole w/MLF 9.5# Brine w/25 # Gel P/BBL.
3. Spot 40sx plug fr/3600-3400(Queen)
4. Spot 40sx plug fr/2600-2400(B-salt, Yates) Tag @ 2375
5. Spot 40sx plug fr/1200-1000(T-salt)Tag@1010(ok w/OCD)sqz 100sx Bad csg@371-359(10 3/4 shoe)Tag@125
6. Perf 4 holes @ 125 circ cmt fr/125 to surf 7 X 10 3/4 Tag @ surf
7. Install dry hole marker. 12-04-02

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE MANAGER/SUNSET DATE 12-04-02

Type or print name Jimmy BAGLEY Telephone No. 915 520-8756
(This space for State use) [Signature]

APPROVED BY GARY W. WINK TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE FEB 25 2003
Conditions of approval, if any:

GWW