SANTA FE SANTA		٦		
NEW MEXICO OIL CONSERVATION COMMISSION Consider Co	NO. OF COPIES RECEIVED	-		Form C-103 Supersedes Old
SUNDRY NOTICES AND REPORTS ON WELLS SEARCH SET THE PROTECT OF THE P		NEW MEXICO OIL CON	SERVATION COMMISSION	
Sundry Notices And Reports on Wells Sundry Notices And Reports on West Dollarhide Queen Sand Unit A result of the Gold Company West Dollarhide Queen Sand Unit A result of the West Dollarhid		THE WEXTED OIL CON	SERVATION COMMISSION	Effective 1-1-65
SUNDRY NOTICES AND REPORTS ON WELLS SUNDRY NOTICES AND REPORTS ON WELLS SUNDRY NOTICES AND REPORTS ON WELLS SEE TO SUND HE THE SECRET SURVEY SECRET SURVEY SURVE		7		5a. Indicate Type of Lease
SUNDRY NOTICES AND REPORTS ON WELLS ONLY WEST DELIBERATION FOR SHARP SHARP SHAPE SH		7		State XX Fee.
SUNDRY NOTICES AND REPORTS ON WELLS Control Control	OPERATOR	7		5. State Oil & Gas Lease No.
West Dollarhide Queen Sand Unit Actives of Congress of				B-1732
West Dollarhide Queen Sand Un: Now of Lorentz Now	SUND	RY NOTICES AND REPORTS OF	WELLS BACK TO A DIFFERENT RESERVOIR.	
Skelly Oil Company Skelly Oil Company Authors of Company Notice of Receiver of South The West oil 15, Midland, Texas 79701 4. Location of West oil Company The West oil Scenario of West oil Company The West oil Scenario of South The South oil Scenario of South oil Scenario oil oil	1.	ATION FOR PERMIT -" (FORM C-101) FOR S.		
ALTERIOR CASHMENT P. O. Box 1351, Midland, Texas 79701 4. Location of Med. 5. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: 6. Substitution of Med. 7. Location of	WELL WELL WELL	OTHER+	West	
P. O. Box 1351, Midland, Texas 79701 4. Location of Well 4. Locati			West	
10. Field and Pool, or Wildeen		d. Texas 79701		
The West the, section 33 township 245 many 38E m	4. Location of Well		220	10. Field and Pool, or Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 3168' GR Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM NEW CIAL WORK TEMPORABILY ABANDON PULL ON ALTER CASING OTHER 17. Check The Proposed of Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of storting any propose have been experienced. The cost of operating wells in this area has become excessive, and we propose plugging this well as follows: 1) Rig up pulling unit. Pull rods and tubing. 2) Sat 7" bridge plug at 3575'. 3) Circulate hole with 10f mud. 4) Spot 10 sacks cement on top of bridge plug. 5) Spot 10-sack cement across top of salt section at 1211'. 6) Spot 10-sack cement across top of salt section at 1211'. 6) Spot 10-sack cement will be filled with 10f mud. 18. I hereby certify that the information above is true and complete to the best of my knowledge and better. NOV. 10, 1972 Orig. Signed by John Remyan Viria	UNIT LETTER	660 FEET FROM THE SOUEN	LINE AND 330 FEET F	DOTTSLUIGE GREEN
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMAINAL WORK PULL AND ABANDON PULL OR ALTER CASING CHANGE PLANS CHA	THE West LINE, SEC	rion33rownship248	RANGE 38E	мрм.
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK TEMPORATILY ABANDON PULL OR ALTER CASING OTHER OTHER OTHER THIS well is in the lower one—third of the unit area in which water break through problems have been experienced. The cost of operating wells in this area has become excessive, and we propose plugging this well as follows: 1) Rig up pulling unit. Pull rods and tubing. 2) Sat 7" bridge plug at 3575". 3) Circulate hole with 10# mud. 4) Spot 10 sacks cement on top of bridge plug. 5) Spot 100 sacks cement across top of salt section at 1211'. 6) Spot 10-sack cement plug at surface. 7) Set marker. All intervals not cemented will be filled with 10# mud. 16.1 hereby certify that the information above is true and complete to the best of my knowledge and belief. Orig. Signed by John Renyan Title Orig. Signed by John Renyan Title ALTERING CASING REMEDIAL NOR. ALTERING CASING PLUS AND ABANDONNET ALTERING CASING PLUS AND ABANDONNET PLUS		15. Elevation (Show whether		12. County
Check Appropriate Box 10 Indicate Nature of Notice, Report of Other Data NOTICE OF INTENTION TO: DEFECTION REMEDIAL WORK TEMPORABILITY ABANDON PULL OR ALTER CADING OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose unork) SEE RULE 1103. This well is in the lower one—third of the unit area in which water break through problems have been experienced. The cost of operating wells in this area has become excessive, and we propose plugging this well as follows: 1) Rig up pulling unit. Pull rods and tubing. 2) Set 7" bridge plug at 3575'. 3) Circulate hole with 10f mud. 4) Spot 10 sacks cement on top of bridge plug. 5) Spot 10-sack cement across top of salt section at 1211'. 6) Spot 10-sack cement plug at surface. 7) Set marker. All intervals not cemented will be filled with 10f mud. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. Nov. 10, 1972 Orig. Signed by John R-myan Title Orig. Signed by John R-myan Title ONE SET WILL THE TOTAL WORK ALTERIOR CASING ALTERIOR CA			3168' GR	Lea
PLUS AND ABANDON ACTION BENEFIT OF THE STATE	Check	Appropriate Box To Indicate	Nature of Notice, Report or	Other Data
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose users) SEE RULE 1103. This well is in the lower one—third of the unit area in which water break through problems have been experienced. The cost of operating wells in this area has become excessive, and we propose plugging this well as follows: 1) Rig up pulling unit. Pull rods and tubing. 2) Set 7" bridge plug at 3575'. 3) Circulate hole with 10# mud. 4) Spot 10 sacks cement on top of bridge plug. 5) Spot 100 sacks cement across top of salt section at 1211'. 6) Spot 10-sack cement plug at surface. 7) Set marker. All intervals not cemented will be filled with 10# mud. 18.1 hereby certify that the information above is true and complete to the best of my knowledge and belief. Nov. 10, 1972 Orig. Signed by John Runyan Title Orig. Signed by John Runyan Title APPROVED BY OTHER NOV. 13 10	NOTICE OF	INTENTION TO:	SUBSEQU	ENT REPORT OF:
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose users) SEE RULE 1103. This well is in the lower one—third of the unit area in which water break through problems have been experienced. The cost of operating wells in this area has become excessive, and we propose plugging this well as follows: 1) Rig up pulling unit. Pull rods and tubing. 2) Set 7" bridge plug at 3575'. 3) Circulate hole with 10# mud. 4) Spot 10 sacks cement on top of bridge plug. 5) Spot 100 sacks cement across top of salt section at 1211'. 6) Spot 10-sack cement plug at surface. 7) Set marker. All intervals not cemented will be filled with 10# mud. 18.1 hereby certify that the information above is true and complete to the best of my knowledge and belief. Nov. 10, 1972 Orig. Signed by John Runyan Title Orig. Signed by John Runyan Title APPROVED BY OTHER NOV. 13 10		ļ .		
OTHER OT	PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
17. Describe Proposed of Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) SEE ROLE 1103. This well is in the lower one—third of the unit area in which water break through problems have been experienced. The cost of operating wells in this area has become excessive, and we propose plugging this well as follows: 1) Rig up pulling unit. Pull rods and tubing. 2) Set 7" bridge plug at 3575'. 3) Circulate hole with 10# mud. 4) Spot 10 sacks cement on top of bridge plug. 5) Spot 10 sacks cement across top of salt section at 1211'. 6) Spot 10-sack cement plug at surface. 7) Set marker. All intervals not cemented will be filled with 10# mud. 18.1 hereby certify that the information above is true and complete to the best of my knowledge and belief. Orig. Signed by John Renayan Jo	TEMPORARILY ABANDON	<u></u>	1	PLUG AND ABANDONMENT
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) SEE RULE 1103. This well is in the lower one—third of the unit area in which water break through problems have been experienced. The cost of operating wells in this area has become excessive, and we propose plugging this well as follows: 1) Rig up pulling unit. Pull rods and tubing. 2) Set 7" bridge plug at 3375'. 3) Circulate hole with 10# mud. 4) Spot 10 sacks cement on top of bridge plug. 5) Spot 100 sacks cement across top of salt section at 1211'. 6) Spot 10-sack cement plug at surface. 7) Set marker. All intervals not cemented will be filled with 10# mud. 18.1 hereby certify that the information above is true and complete to the best of my knowledge and belief. Orig. Signed by John Renayan John Ren	PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	
This well is in the lower one-third of the unit area in which water break through problems have been experienced. The cost of operating wells in this area has become excessive, and we propose plugging this well as follows: 1) Rig up pulling unit. Pull rods and tubing. 2) Set 7" bridge plug at 3575'. 3) Circulate hole with 10# mud. 4) Spot 10 sacks cement on top of bridge plug. 5) Spot 100 sacks cement across top of salt section at 1211'. 6) Spot 10-sack cement plug at surface. 7) Set marker. All intervals not cemented will be filled with 10# mud. 18,1 hereby certify that the information above is true and complete to the best of my knowledge and belief. Orig. Signed by John Renyan JITLE Lead Clerk DATE NOV. 10, 1972		F	OTHER	
This well is in the lower one-third of the unit area in which water break through problems have been experienced. The cost of operating wells in this area has become excessive, and we propose plugging this well as follows: 1) Rig up pulling unit. Pull rods and tubing. 2) Set 7" bridge plug at 3575'. 3) Circulate hole with 10f mud. 4) Spot 10 sacks cement or top of bridge plug. 5) Spot 100 sacks cement across top of salt section at 1211'. 6) Spot 10-sack cement plug at surface. 7) Set marker. All intervals not cemented will be filled with 10f mud. 18.1 hereby certify that the information above is true and complete to the best of my knowledge and belief. 18.1 hereby certify that the information above is true and complete to the best of my knowledge and belief. 18.2 Lead Clerk Orig. Signed by John Ronyan JILLE OATE NOV. 13 19	OTHER]	
This well is in the lower one-third of the unit area in which water break through problems have been experienced. The cost of operating wells in this area has become excessive, and we propose plugging this well as follows: 1) Rig up pulling unit. Pull rods and tubing. 2) Set 7" bridge plug at 3575'. 3) Circulate hole with 10# mud. 4) Spot 10 sacks cement or top of bridge plug. 5) Spot 100 sacks cement across top of salt section at 1211'. 6) Spot 10-sack cement plug at surface. 7) Set marker. All intervals not cemented will be filled with 10# mud. 18.1 hereby certify that the information above is true and complete to the best of my knowledge and belief. Title Lead Clerk Orig. Signed by John Ronyan J	17 Describe Crowned or Completed	Operations (Clearly state all pertinent de	stails and give pertinent dates inclu	ding estimated date of starting any proposed
Orig. Signed by John Runyan TITLE Lead Clerk DATE NOV. 10, 1972 NOV 13 19	have been experienced. we propose plugging the state of the second of th	The cost of operating his well as follows: It. Pull rods and tubing at 3575'. Ith 10# mud. Internation top of bridge plugment across top of salt and plug at surface. Ented will be filled with	wells in this area has section at 1211'. 10# mud.	
Orig. Signed by John Runyan TITLE NOV 13 19	18. I hereby certify that the informati	on above is true and complete to the bes	of my knowledge and belief.	
APPROVED BY John Runyan TITLE DATE NUV 13 15	SIGNED	TITLE	Lead Clerk	Nov. 10, 1972
APPROVED BY John Runyan TITLE DATE NUV 13 15		Onia Signed has		
APPROVED BY				NOV 1.3.197
	APPROVED BY	Geologist		DATE / TO IJ

CONDITIONS OF APPROVAL, IF ANY: