NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

MISCELLANEOUS NOTICES

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Notice by Checking Below

TICE OF INTENTION CHANGE PLANS	No Te	tice of Intention to Mporarily Abandon Well	NOTICE OF INTENTION TO DRILL DREPER	
TICE OF INTENTION PLUG WELL		tige of Intention Plug Back	Notice of Intention to Set Liner	
tice of Intention Squeeze		tice of Intention Acidize	Notice of Intention to Shoot (Nitro)	
tice of Intention Gun Perforate	1 1	tice of Intention Ther)	NOTICE OF INTENTION (OTHER)	
IL CONSERVATION COMM	ISSION	Hobbs, New Marico	December 9 ₅	, 1964
ntlemen: Following is a Notice of Intr Elsoyn C	ention to do cert	ain work as described below at Hale S	tete Well No. 3 in	H (Unit)
NR 1/ SE 1/4 of S	2	T 25 S R 37 E	NMPM., North Justis	Pc
(40-acre Subdivision)				
planned to undertai	te repair o four casing emple brid	T THE LEEK AS IOLLOW	casing strings near 4950' &	
with frac 3. Perforate 4. Squeese c After dri 5. Retrieve Blin Fuse	sand. Ter casing str ement leak 11 out. all bridge ebry - flow elman - flo	nt all strings to 200 ring 1 with one orien in stages until stri plugs and return all ring in 2 7/8" csg. owing thru 1 1/2" IJ	to parg. inted hole at leak point. ing 1 will hold 2000 paig wate 1 sones to production: tbg landed on retrievable par	n pressu cker neej
with frac 3. Perforate 4. Squeese c After dri 5. Retrieve Blin Fuse Mont	sand. Ter casing str ament leak 11 out. all bridge ebry - flor 68 oya - pump at 7.	nt all strings to 200 ring 1 with one orien in stages until stri ring in 2 7/8" csg. owing thru 1 1/2" IJ 50" in 3 1/2" csg. ing with Kobe with 1 180" in 2 7/8" csg.	<pre>nted hole at leak point. ing 1 will hold 2000 psig wate 1 sones to production: tbg landed on retrievable par " IJ tbg landed on production Over Elwyn C. Hale</pre>	n pressu cker neej
vith frac 3. Perforate 4. Squeese c After dri 5. Retrieve Blin Fuse Mont	sand. Ter casing str ament leak 11 out. all bridge ebry - flor 68 oya - pump at 7.	nt all strings to 200 ring 1 with one orien in stages until stri ring in 2 7/8" csg. owing thru 1 1/2" IJ 50" in 3 1/2" csg. ing with Kobe with 1 180" in 2 7/8" csg.	nted hole at leak point. ing 1 will hold 2000 psig wate 1 sones to production: tbg landed on retrievable par " IJ tbg landed on production Over Klaryn C. Hale 7. Company or Operator M. K. Armith	kr pressu cker near retainer
Approved	sand. Ter casing str ment leak il out. all bridge ebry - flow alman - flow 68; oya - pump at 7.	nt all strings to 200 ring 1 with one orien in stages until stri- plugs and return all ring in 2 7/8" csg. owing thru 1 1/2" IJ 50" in 3 1/2" csg. ing with Kobe with 1 180" in 2 7/8" csg. 	<pre>nted hole at leak point. ing 1 will hold 2000 psig wate 1 sones to production: tbg landed on retrievable par " IJ tbg landed on production Over Elwyn C. Hale y Company or Operator</pre>	kr pressu cker near retainer
Approved Approved Approved Approved Approved OIL CONSERVATION COM	sand. Ter casing str ement leak ll out. all bridge ebry - flor elman - flor 68; coya - pump at 7.	nt all strings to 200 ring 1 with one orien in stages until stri- wing in 2 7/8" csg. owing thru 1 1/2" IJ 50° in 3 1/2" csg. ing with Kobe with 1 180° in 2 7/8" csg. By Position	nted hole at leak point. ing 1 will hold 2000 psig wate 1 sones to production: tbg landed on retrievable par " IJ tbg landed on production Over Elsyn C. Hale <i>J. K. Armich</i> Agent. Send Communications regarding well to	kr pressu cker near retainer
with frac 3. Perforate 4. Squeese c After dri 5. Retrieve Blin Fuse Mont Approved	sand. Ter casing str ement leak ll out. all bridge ebry - flor elman - flor 68; coya - pump at 7.	nt all strings to 200 ring 1 with one orien in stages until stri- plugs and return all wing in 2 7/8" csg. owing thru 1 1/2" IJ 50' in 3 1/2" csg. ing with Kobe with 1 180' in 2 7/8" csg. By Position	<pre>nted hole at leak point. ing 1 will hold 2000 psig wate 1 sones to productions tbg landed on retrievable par " IJ tbg landed on production Over Elseyn C. Hale Agent. Send Communications regarding well to Elseyn C. Hale</pre>	kr pressu cker near retainer

McKee - ilouing thru l l/2" IJ thg hung near 8100" in 3 l/2" casing.

٠

•

•

•

•

6. Froques all sons until loads recovered and stabilized. Aun communication test.

<u>.</u>

,

•

•