

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-20039

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
ARCO OIL AND GAS COMPANY

3. Address of Operator
P. O. Box 1610, Midland, Texas 79702

4. Well Location
Unit Letter G : 1980 Feet From The North Line and 1650 Feet From The East Line

Section 25 Township 25 S Range 37 E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3071' DF

7. Lease Name or Unit Agreement Name

Wimberley
Ida Wimberley

8. Well No.
14

9. Pool name or Wildcat
Justis Blinbry Langle mitty
SR-01-01
Subb Brinkard R 9745 11/1/92

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRU PU. ND wellhead. NU BOP.
2. TIH (Blinbry side) w/CIBP & set @ 5284'. Dump bail 35' of cmt on CIBP.
3. TIH (Seven Rivers Queen Side) w/CIBP & set @ 2994'. Dump bail 35' of cmt on CIBP.
4. Chemical cut both strings of tbq @ 1950' & T00H w/both strings of tbq.
5. Spot 30 sx of C1 'C' neat cmt f/1950' - 1850'.
6. Spot a 100' 30 sx C1 'C' neat cmt plug f/900 - 800' (surf shoe).
7. Spot a 10 sx C1 'C' neat cmt plug f/40' to surf.
8. Cut off wellhead & anchors. Weld on plate w/value. Clean location.

PLUG 100' CMT PLUG IN BLINBRY STRING @
2994 - 2884

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Chris E. Humes TITLE Drilling Engineer DATE 11-24-92

TYPE OR PRINT NAME Chris E. Humes 915/688-5477 TELEPHONE NO.

(This space for State Use) ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE NOV 30 '92

CONDITIONS OF APPROVAL, IF ANY:

WELLBORE SCHEMATIC

Ida Wimberley #14

AHC/ARCO Oil and Gas Company
1980' FNL & 1650' FEL (G)

Sec 25, T-25S, R-37E, Lea Co., NM
KB-3072'

Spudded 02/09/63

Completed 03/01/63

17-1/2" Hole.
14" casing @ 20'.
Set w/30 sxs cmt. Circ.

11" Hole.
8-5/8" casing @ 850'.
Set w/400 sxs cmt. Circ.

TOC @ 2002' by TS

7Rvrs Qn Perfs @ 3069' to 3247'.

Blinbry perfs 5359'-5425'.
TA'd 08/83

PBD @ 5441'.

PBD @ 5464'.
7-7/8" hole.
2-7/8" tbg @ 5495'.

7-7/8" hole.
2-7/8" tbg @ 5497' w/900 sxs cmt.

TD @ 5500'.