

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION  
 Orig<sup>4</sup>cc: OCC, Hobbs  
 cc: Southern Region (West Texas)  
 cc: file

Form C-103  
 Supersedes Old  
 C-102 and C-103  
 Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>	
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator SINCLAIR OIL CORPORATION	8. Farm or Lease Name Wimberly WN
3. Address of Operator P. O. Box 1920, Hobbs, New Mexico 88240	9. Well No. 8
4. Location of Well UNIT LETTER C, 2310 FEET FROM THE West LINE AND 660 FEET FROM THE North LINE, SECTION 23 TOWNSHIP 25S RANGE 37E NMPM.	10. Field and Pool, or Wildcat Justis Blinebry
15. Elevation (Show whether DF, RT, GR, etc.) 3090.8' GR	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	OTHER <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
OTHER Perf. higher in Blinebry & break down w/acid and SOF. Same Formation. <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Presently completed in Blinebry 5352-5451'. TD Drilled 5525', PBTD 5515'.

PROPOSE TO: Set Ret B.P. @ 5320'. Perf w/2-3/8" jets @ approx. intervals 5167, 5173, 5176, 5182, 5184, 5189, 5197, 5198, 5214, 5232, 5234, 5237, 5239, 5242, 5248, 5262, 5264, 5282 and 5300'. Breakdown w/approx. 2,000 gals. BDA plus ball sealers and frac w/approx. 30000 gals. refined oil plus approx. 30,000# sand. Recover load, pull Ret. B.P. and produce w/all perfs. together.

(ch JWR-T. Ak 5147')

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>[Signature]</u>	TITLE <u>Superintendent</u>	DATE <u>2-10-69</u>
APPROVED BY <u>[Signature]</u>	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		