

3. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
State Oil & Gas Lease No.	

B-158

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT --" (FORM C-10) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		7. Unit Agreement Name
2. Name of Operator <b>TEXACO, Inc.</b>		8. Farm or Lease Name <b>N.M. BZ St. NCT-10</b>
3. Address of Operator <b>P.O. Box 728 - Hobbs, New Mexico 88240</b>		9. Well No. <b>3</b>
4. Location of Well UNIT LETTER <b>L</b> <b>989</b> FEET FROM THE <b>West</b> LINE AND <b>1980</b> FEET FROM THE <b>South</b> LINE, SECTION <b>2</b> TOWNSHIP <b>25-S</b> RANGE <b>37-E</b> NMPM.		10. Field and Pool, or Wildcat <b>Justis Blinbry</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3170 DF</b>		2. County <b>Lea</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Pull rods and pump from Blinbry.
2. Fish rods from Drinkard.
3. Perforate Drinkard 5651-5651 w/4 JSPF.
4. Run rods and pump in Drinkard string and use Blinbry string as vent string.
5. Test and place on production in Blinbry zone.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Asst. Dist. Supt. DATE June 5, 1974

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: