Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

N.M. Oil Cans. Division 1625 N. Fignch Dr. ECOM ADDROVED Hobbs

,	NM	88240 OMB No. 1004-0135 Expires November 30, 200
		5 Leans Carial No.

LC-032511-F

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an If Indian, Allottee or Tribe Name abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit or CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on reverse side Type of Well 🛣 Oil Well 🗌 Gas Well 🔲 Other Well Name and No. SOUTH JUSTIS UNIT "B" WELL #12 Name of Operator HENRY PETROLEUM LP 9. API Well No. 30-025-20547 3b. Phone No. (include area code) 3525 ANDREWS HWY - MIDLAND TX 79703-5000(915)694-3000 10. Field and Pool, or Exploratory Area JUSTIS-BLBRY-TUBB-DRINKARD 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
1650' FNL & 2310' FWL - UNIT LETTER F - SECTION 11-25S-37E 11. County or Parish, State **LEA COUNTY NEW MEXICO** 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Acidize ☐ Deepen Production (Start/ Resume) ☐ Water Shut-Off Notice of Intent ☐ Fracture Treat ☐ Well Integrity ☐ Reclamation Alter Casing Subsequent Report New Construction Recomplete Other ___ Casing Repair Change Plans Plug and Abandon Temporarily Abandon ☐ Final Abandonment Notice Convert to Injection ☐ Plug Back ☐ Water Disposal 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) 1.) SET CIBP AT 5520'. PERFORATE ADDITIONAL INTERVALS 5330-5347, 5409-5440, 5474-5484. 3.) ACIDIZE NEW PERFORATIONS 5330-5484 W/3000 GALS ACID. SPOT SAND ON TOP OF CIBP FROM 5520-5290 & SQUEEZE UPPER PERFS. 5114-5266 W/225 SX. WOC 24 HRS. & THEN CLEAN OUT SAND TO 5500 & CIRC. HOLE CLEAN. **RUN INJECTION EQUIPMENT & SET INJECTION PACKER AT 5025'** 7.) NOTIFY NMOCD AND RUN MIT TEST AT 500 PSI FOR 30". PLACE WELL ON INJECTION. I hereby certify that the foregoing is true and correct Name (Printed/Typed) **ROY R. JOHNSON** REGULATORY TECH. Date Signature 10/25/2001 THIS SPACE FOR FEDERAL OR STATE OFFICE USE Date Approved by Title

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease

which would entitle the applicant to conduct operations thereon.

Office